





### General information

Make	PEUGEOT
Model	107 ACTIVE
Colour	Black
Year of manufacture	2013
Top speed	100 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	А







# Internet history


Entry 1

Date

Pictures

2021-11-19

12



source: cargurus.co.uk



### MOT history

MOT expiry date	2025-01-24
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	14
Total items failed	3

MOT #10		2024-01-18 16:43
MOT test	number	516682716923
Result		Passed
Next expi	ry date	2025-01-24
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

#### 2024-01-18 13:34 MOT #9 533858880783 **MOT test number** Result × Failed Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Fail Hazard warning switch inoperative (4.4.2 (a) (ii)) Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Nearside Front Road wheel slightly distorted (5.2.2 (c) (i)) Advice

MOT #8	2023-01-19 07:29
MOT test number	581142066575
Result	✓ Passed





MOT #7	2022-01-20 12:49
MOT test number	503649353460
Result	✓ Passed
МОТ #6	2021-01-25 09:53
MOT test number	316575995738
Result	✓ Passed

	2019-05-08 15:06
number	296678501875
	✓ Passed
Nearside Rear Tyre slightly damaged slightly out of shape (5.2.3 (d) (ii))	
Front wiper blade split at end	
Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))	
Nearside Front Tyre worn close to legal limit/worn on edge 2mm tread (5.2.3 (e)	))
	Nearside Rear Tyre slightly damaged slightly out of shape (5.2.3 (d) (ii)) Front wiper blade split at end Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

МОТ #4	2018-04-10 14:38
MOT test number	275992084253
Result	✓ Passed
<b>Advice</b> Nearside Front Anti-roll bar linkage rubber mounting deteriorated but movement (2.4.G.2)	It not resulting in excessive
Advice Nearside Front Lower Suspension arm rubber bush deteriorated but movement (2.4.G.2)	not resulting in excessive
<b>Advice</b> Offside Front Anti-roll bar linkage rubber mounting deteriorated but movement (2.4.G.2)	not resulting in excessive

МОТ #3	2017-03-22 15:50
MOT test number	190816545238
Result	✓ Passed



YD13HBH
report date: 2024-03-28

🗸 Passed

MOT #2	2017-03-20 16:41
MOT test number	703120981719
Result	🗙 Failed
AdviceOffside Front Road wheel slightly damaged (4.2.A.1a)FailNearside Front Outer Tyre has a cut in excess of the requirements decords wall cuts around wall (4.1.D.1a)	ep enough to reach the ply or
MOT #1 MOT test number	2016-04-06 16:37 270765488441

Result



Tax & MOT check

✓ Taxed Tax due: 1 August 2024	✓ MOT Expires: 24 January 2025
Tax status	Valid until 1 August
Days left	95
MOT expiry date	24 January 2025
Full MOT history	See MOT history
Tax calculation	
Vehicle class	48
David	٨

Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable





#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

ARMP
AMPL
F Stores
NE
ant

#### Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





### Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
************	
********	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-03-22
Last registration	2024-01-18
Complete history	See info



Registration #1	2013-03-22	28 mi
Registration #2	2016-04-06	10.381 mi
Registration #3	2017-03-20	13.533 mi
Registration #4	2017-03-22	13.562 mi
Registration #5	2018-04-10	18.967 mi
Registration #6	2019-05-08	22.592 mi
Pagistration #7		
Registration #7		
Registration #8		10.000 est
-		11.117 es
Registration #8		10.000 est 10.000 est 10.000 est
Registration #8 Registration #9		10.000 est 10.000 est 10.000 est 10.000 est





# Car features

S0225	Air conditioning
\$0295	
S0482	
S0501	
\$0566	
\$0567	
\$0569	

# Safety ratings

NCAP rating	****
Adult	68%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	66%
Video	see crash video



Dimensions & weight	
Width	1855 mm
Height	1470 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	900 kg
Max. allowed weight	1180 kg
Additional information	
Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12