



report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO 1700 SE ECOFLEX
Colour	White
Year of manufacture	2011
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-03
Pictures	10
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-07
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	27
Total items failed	7

MOT #14	2023-06-08 15:38
MOT test number	910684083913
Result	✓ Passed
Next expiry date	2024-06-07
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #13	2023-06-08 15:38
MOT test number	852199362234
Result	✗ Failed
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Pass with rectification	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #12	2022-06-08 08:16
MOT test number	917684888005
Result	✓ Passed

**MOT #11** 2021-08-02 12:06**MOT test number** 496157150705**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #10** 2020-07-09 09:50**MOT test number** 112381424835**Result** ✓ Passed**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #9** 2020-07-08 15:40**MOT test number** 177345490183**Result** ✗ Failed**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #8** 2019-07-29 12:57**MOT test number** 263007555438**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear numberplate cracked**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #7** 2018-07-12 09:47**MOT test number** 929662426350**Result** ✓ Passed**MOT #6** 2017-07-17 11:10**MOT test number** 777827419725**Result** ✓ Passed**Advice** Tyre worn close to the legal limit both fronts (4.1.E.1)**MOT #5** 2016-07-12 13:30**MOT test number** 451400466011**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit on 3mm (4.1.E.1)**Advice** Nearside Front Outer Tyre worn close to the legal limit on 2mm (4.1.E.1)**Advice** Front registration plate faded but not likely to be misread (6.3.1d)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #4** 2016-07-12 10:39**MOT test number** 526894398583**Result** ✗ Failed

Fail Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

Advice Nearside Front Outer Tyre worn close to the legal limit on 2mm (4.1.E.1)

Advice Front registration plate faded but not likely to be misread (6.3.1d)

Fail Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Front Tyre worn close to the legal limit on 3mm (4.1.E.1)

Fail Front Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #3 2015-06-30 14:08**MOT test number** 999771585101**Result** ✓ Passed

Notice Slight knock and movement on steering.

MOT #2 2015-06-30 10:33**MOT test number** 529921085164**Result** ✗ Failed

Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Notice Slight knock and movement on steering.

Fail Offside Registration plate lamp not working (1.1.C.1d)

MOT #1 2014-07-01 11:12**MOT test number** 746172284119**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
7 June 2024

Tax status		Valid until 1 June
Days left		32
MOT expiry date		7 June 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Number of owners	1
Current owner since	2019-06-29
Previous owner since	2019-06-29
Number of owners	1
Current owner since	2019-06-29
Previous owner since	2019-06-29

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 KR11EAK
Plate since	2019-06-29
Current registration	 KR11EAK
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-07-25
Last registration	2023-06-08
Complete history	See info



Registration #1	2011-07-25	23 mi
Registration #2	2014-07-01	35.874 mi
Registration #3	2015-06-30	41.799 mi
Registration #4	2015-06-30	41.799 mi
Registration #5	2016-07-12	47.619 mi
Registration #6	2016-07-12	47.619 mi
Registration #7	2017-07-17	50.352 mi
Registration #8	2019-06-20	55.277 mi
Registration #9	2019-06-20	55.277 mi
Registration #10	2019-06-20	55.277 mi
Registration #11	2019-06-20	55.277 mi
Registration #12	2019-06-20	55.277 mi
Registration #13	2019-06-20	55.277 mi
Registration #14	2019-06-20	55.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	4297596