





report date: 2024-03-28

General information

Make	FORD
Model	C-MAX ZETEC TDCI
Colour	Silver
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	204 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/13



report date: 2024-03-28

MOT history

MOT expiry date	2025-01-10
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	28
Total items failed	19

MOT #19	2024-01-11 10:15
MOT test number	704248400494
Result	✓ Passed
Next expiry date	2025-01-10
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #18	2024-01-03 15:53
MOT test number	111790622289
Result	X Failed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	

MOT #17	2023-01-05 16:07
MOT test number	594048589930
Result	✓ Passed

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT test number

Result

Nearside Rear Anti-roll bar linkage insecurely attached (5.3.3 (a) (i))

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Fail Offside Rear Anti-roll bar linkage insecurely attached (5.3.3 (a) (i))

MOT #15

MOT test number

Result

A Passed

MOT #14

MOT test number

643354674888

Result

Minor Offside Obligatory mirror slightly damaged cover missing (3.3 (b) (i))

Advice Offside Rear Passenger seat(s) missing at time of test

MOT #13 2020-12-07 10:05 **MOT** test number 944831549283 Result × Failed **Advice** Nearside Rear tyre wearing on inner edge of tread **Advice** Offside Rear Passenger seat(s) missing at time of test Pass with rectification Nearside Headlamp aim too high (4.1.2 (a)) Windscreen washer provides insufficient washer liquid (3.5 (a)) Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Fail Minor Offside Obligatory mirror slightly damaged cover missing (3.3 (b) (i)) **Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))

CarCheck.co.uk page 3/13



Result

EF59CUG

report date: 2024-03-28

× Failed

MOT #12 2019-12-04 14:59

MOT test number 794979196191

Result ✓ Passed

Minor Offside Obligatory mirror slightly damaged casing on (3.3 (b) (i))

MOT #11 2019-12-04 09:55

MOT test number 429137124188

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Nearside Front Lower Suspension arm pin or bush excessively worn rear bush on (5.3.4 (a) (i))

Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Minor Offside Obligatory mirror slightly damaged casing on (3.3 (b) (i))

Fail Offside Front Lower Suspension arm pin or bush excessively worn rear bush on (5.3.4 (a) (i))

MOT #10 2018-12-13 09:12

MOT test number 650458548214

Result \(\sqrt{Passed} \)

Minor Offside Obligatory mirror slightly damaged unit cover on (3.3 (b) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush on (5.3.4 (a) (i))

Advice Clutch pedal rubber missing

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush on (5.3.4 (a) (i))

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #9 2018-12-13 09:12

MOT test number 547070743401

Result X Failed

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush on (5.3.4 (a) (i))

Pass with rectification Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Pass with rectification Offside Headlamp aim too low (4.1.2 (a))

Minor Offside Obligatory mirror slightly damaged unit cover on (3.3 (b) (i))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush on (5.3.4 (a) (i))

Pass with rectification Nearside Headlamp aim too low (4.1.2 (a))

Advice Clutch pedal rubber missing

MOT #8 2017-12-12 09:27

MOT test number 203822423714

Result \rightarrow Passed

Advice Nearside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #7 2016-12-10 10:18

MOT test number 799602007712

Result

Passed

Advice Front Brake pad(s) wearing thin approx. 3000 miles (3.5.1g)

MOT #6 2016-12-10 10:18

MOT test number 780609714774

Result X Failed

Pass with rectification Nearside Headlamp not working on dipped beam (1.7.5a)

, and a second s

Advice Front Brake pad(s) wearing thin approx. 3000 miles (3.5.1g)

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #5 2015-11-27 11:52

MOT test number 919565629787

Result ✓ Passed

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #4 2014-12-03 13:04

MOT test number 778917334380

Result ✓ Passed

MOT #3 2014-12-03 13:04

MOT test number 445487134486

Result X Failed

Pass with rectification Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Pass with rectification Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #2 2013-11-19 10:32

MOT test number 337603623304

Result

Passed

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2012-12-07 14:28

MOT test number 968362542326

Result

Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 August
Days left	95
MOT expiry date	10 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

More info >

Owner history For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this FORD had different number plates. about of pliates faste since

CarCheck.co.uk page 10/13



EF59CUG report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-12-17
Last registration	2024-01-11
Complete history	See info



Registration #1	2009-12-17	18 mi
Registration #2	2012-12-07	13.161 mi
Registration #3	2013-11-19	16.478 mi
Registration #4	2014-12-03	20.614 mi
Registration #5	2015-11-27	24.211 mi
Registration #6	2016-12-10	31.432 mi
Registration #7	2016-12-10	31.432 mi
Registration #8	2017-12-12	37.695 mi
Registration #9	2018-12-13	43.192 mi
Registration #10	2018-12-13	43.192 mi
Registration #11		11.777 44
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		91.777 es
Registration #18		11.777 es
Registration #19		

More info >

CarCheck.co.uk page 12/13



EF59CUG report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1171 kg
Max. allowed weight	1675 kg

Additional information

Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats	5	
Number of axles CarCheck.co.uk	2 page 13	3/13