



report date: 2024-03-28

## General information

Make	VOLKSWAGEN
Model	AMAROK DC TDI HIGHLINE 4MOTION
Colour	Grey
Year of manufacture	2015
Top speed	108 mph
0 - 60 mph	11.3 seconds
Gearbox	8 speed automatic

## Engine & fuel consumption

Power	178 BHP
Max. torque	420 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	38.2 mpg
Consumption combined	35.3 mpg
CO2 emission	208 g/km
CO2 label	K





Internet history

Entry 1

Date	2022-04-23
Pictures	9
Listing price	<a href="#">View report</a>

**PLUS VAT**

Please be aware that the advertised price for this commercial vehicle is plus 20% VAT.

**Extended warranty available**

Why not extend your warranty provided with any vehicle purchased.

For further details ask a member of our team to help.

**33 Years Experience**

Here at TVM, our helpful team have tons of experience in selling you both during and after purchasing your vehicle.

Buy from the best, hassle free.

**Call now to secure this vehicle**

You can reserve this vehicle now by leaving a deposit.

Don't miss out, call or click to reserve.

source: cargurus.co.uk



## MOT history

MOT expiry date	2024-08-03
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	9
Total items failed	1

MOT #7	2023-08-04 10:06
MOT test number	956555721245
Result	✓ Passed
Next expiry date	2024-08-03
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #6	2023-07-31 15:23
MOT test number	302128532554
Result	✗ Failed
MAJOR	Headlamp aim too low (4.1.2 (a))
MAJOR	Front Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))
MAJOR	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
MAJOR	Central Rear Seat belt not functioning as intended (7.1.2 (c))
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
MAJOR	Nearside Rear Direction indicator adversely affected by the operation of another lamp (4.4.3 (b))
MAJOR	Stop lamp(s) not working both outer (4.3.1 (a) (ii))
MAJOR	Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))



<b>MOT #5</b>	2022-05-12 08:20
---------------	------------------

<b>MOT test number</b>	460585117739
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2022-05-12 08:20
---------------	------------------

<b>MOT test number</b>	846551738681
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Pass with rectification</b>	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
--------------------------------	---

<b>MOT #3</b>	2021-10-09 12:21
---------------	------------------

<b>MOT test number</b>	137428202487
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2020-03-12 10:26
---------------	------------------

<b>MOT test number</b>	734576781659
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2019-01-10 13:58
---------------	------------------

<b>MOT test number</b>	440203805316
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

X

Untaxed

Tax expired:  
1 May 2023

✓

MOT

Expires:  
3 August 2024

Tax status	Expired at 1 May 2023
Days left	363 days too late
MOT expiry date	3 August 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>GD65HYB</b>
Plate since	2019-06-29
Current registration	 <b>GD65HYB</b>
Plate since	2019-06-29

More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-11-20
Last registration	2023-08-04
Complete history	<a href="#">See info</a>



Registration #1	2015-11-20	27 mi
Registration #2	2019-01-10	57.487 mi
Registration #3	2020-03-12	68.107 mi
Registration #4	2021-10-09	105.016 mi
Registration #5	2023-08-04	105.016 mi
Registration #6	2023-08-04	105.016 mi
Registration #7	2023-08-04	105.016 mi
Registration #8	2023-08-04	105.016 mi
Registration #9	2023-08-04	105.016 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	64%
Pedestrian	47%
Safety systems	57%
Overall rating	71%
Video	<a href="#">see crash video</a>



Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	CSHA102081