




report date: 2024-03-28

General information

Make	CITROEN
Model	BERLINGO HDI XTR
Colour	Grey
Year of manufacture	2010
Top speed	100 mph
0 - 60 mph	14.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	56.5 mpg
Consumption combined	49.6 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-01-29
Pictures	0
Listing price	View report

source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-04-09
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	25
Total items failed	9

MOT #17	2024-04-10 10:55
MOT test number	502870482183
Result	✓ Passed
Next expiry date	2025-04-09
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #16	2023-03-31 10:35
MOT test number	561233093596
Result	✓ Passed
Advice	Rear brake pads wearing thin

MOT #15	2022-04-01 10:16
MOT test number	297580824337
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #14** 2022-04-01 10:16**MOT test number** 866721540324**Result** ✗ Failed**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #13** 2021-02-05 12:08**MOT test number** 755292837448**Result** ✓ Passed**MOT #12** 2020-02-13 14:43**MOT test number** 899568367867**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #11** 2019-01-31 12:10**MOT test number** 980341809071**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**Advice** Exhaust emits black smoke during acceleration just passed (8.2.1.2 (g))**MOT #10** 2018-02-16 10:13**MOT test number** 841487235220**Result** ✓ Passed**Advice** Nearside Front tyre worn on outer shoulder**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #9** 2018-02-16 10:13**MOT test number** 999962959320**Result** ✗ Failed**Pass with rectification** Offside Front Front position lamp(s) not working dip beam (1.1.A.3b)**Advice** Nearside Front tyre worn on outer shoulder**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Pass with rectification** Rear Registration plate lamp not working both sides (bulb holders in poor condition locking tabs missing) (1.1.C.1d)**MOT #8** 2017-02-13 14:10**MOT test number** 768413192944**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #7** 2017-02-13 10:29**MOT test number** 690975715203**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Wipers poor**Advice** Child Seat fitted not allowing full inspection of adult belt**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Rear Nail in tyre**Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)**MOT #6** 2016-02-24 11:22**MOT test number** 546971881786**Result** ✓ Passed

**MOT #5** 2016-02-24 08:57**MOT test number** 610714741722**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #4** 2015-02-27 12:43**MOT test number** 756148055094**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2015-02-27 12:43**MOT test number** 717318655029**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Offside Front Headlamp not working on dipped beam (1.7.5a)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Front Headlamp aim too high (1.8)**MOT #2** 2014-03-24 15:44**MOT test number** 407173884055**Result** ✓ Passed



MOT #1	2013-03-19 15:44
MOT test number	116148673410
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
9 April 2025

Tax status	Valid until 1 September
Days left	124
MOT expiry date	9 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	WV10NNK
Plate since	2019-09-29
Current registration	WV10NNK
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-03-31
Last registration	2024-04-10
Complete history	See info



Registration #1	2010-03-31	12 mi
Registration #2	2013-03-19	33.565 mi
Registration #3	2014-03-24	43.408 mi
Registration #4	2015-02-27	49.833 mi
Registration #5	2016-02-24	58.265 mi
Registration #6	2016-02-24	58.266 mi
Registration #7	2017-02-13	69.332 mi
Registration #8	2017-02-13	69.333 mi
Registration #9	2018-02-16	78.427 mi
Registration #10	2019-03-20	85.377 mi
Registration #11	2019-03-20	85.377 mi
Registration #12	2019-03-20	85.377 mi
Registration #13	2019-03-20	85.377 mi
Registration #14	2019-03-20	85.377 mi
Registration #15	2019-03-20	85.377 mi
Registration #16	2019-03-20	85.377 mi
Registration #17	2019-03-20	85.377 mi
Registration #18	2019-03-20	85.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1803 mm
Length	4380 mm
Wheel base	2728 mm
Kerb weight	1407 kg
Max. allowed weight	2040 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBBU0076079