



report date: 2024-03-29

General information

Make	KIA
Model	RIO CRDI SPORT
Colour	Black
Year of manufacture	2009
Top speed	110 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	235 Nm at 2.000 rpm
Engine capacity	1.493 cc
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-06-18
Pictures	24
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-05
MOT pass rate	57 %
MOT passed	12
Failed MOT tests	9
Total advice items	66
Total items failed	25

MOT #21	2023-12-29 16:57
MOT test number	132281508567
Result	✓ Passed
Next expiry date	2025-01-05
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))

MOT #20	2023-12-28 15:01
MOT test number	470516625550
Result	✗ Failed
Fail	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))
Fail	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Fail	Power steering pipe/hose leaking (2.1.5 (a))

**MOT #19**

2022-12-20 15:15

MOT test number

408849932726

Result

✓ Passed

- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front reg plate broken
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement wishbone front bush bonding deteriorating (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn smooth on edge (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement wishbone front bush bonding deteriorating (5.3.4 (a) (i))
- Advice** Parking brake travel has just met min requirements it may need adjustment or repair
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))

MOT #18

2022-12-14 10:53

MOT test number

980902547479

Result

✗ Failed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement wishbone front bush bonding deteriorating (5.3.4 (a) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))
- Advice** Front reg plate broken
- Fail** Nearside Front Brake pipe excessively corroded (1.1.11 (c))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement wishbone front bush bonding deteriorating (5.3.4 (a) (i))
- Advice** Parking brake travel has just met min requirements it may need adjustment or repair
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn smooth on edge (5.2.3 (e))

**MOT #17**

2022-01-06 15:30

MOT test number

293447254396

Result

✓ Passed

Advice Front Exhaust mounting defective (6.1.2 (a))**Advice** Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**MOT #16**

2020-12-31 09:24

MOT test number

582357138866

Result

✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge bold on inner shoulder (5.2.3 (e))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #15**

2020-12-15 18:03

MOT test number

825992039483

Result

✗ Failed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge bold on inner shoulder (5.2.3 (e))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Offside Parking brake inoperative on one side (1.4.1 (a))

**MOT #14** 2019-06-28 08:02**MOT test number** 112159845767**Result** ✓ Passed

- Advice** Brake pad(s) wearing thin both front (1.1.13 (a) (ii))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))
- Advice** Oil leak

MOT #13 2019-06-18 12:51**MOT test number** 447830219714**Result** ✗ Failed

- Advice** Oil leak
- Fail** Offside Brake pipe excessively corroded front to rear (1.1.11 (c))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords inner side wall deep cut (5.2.3 (d) (i))
- Advice** Offside Front tyre worn inner edge
- Fail** Nearside Brake pipe excessively corroded front to rear (1.1.11 (c))
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords inner side wall deep cut (5.2.3 (d) (i))
- Advice** Brake pad(s) wearing thin both front (1.1.13 (a) (ii))
- Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #12 2018-05-30 16:58**MOT test number** 601739980153**Result** ✓ Passed



MOT #11	2018-05-30 09:17
MOT test number	153503869699
Result	✗ Failed
Fail	Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Offside Front Position lamp not working (4.2.1 (a))
Fail	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #10	2017-06-06 11:12
MOT test number	113260876400
Result	✓ Passed
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened corroded (3.5.1i)
Advice	Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)
Advice	Center brake light not working
Advice	N\s\r slight brake bind
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Rear Tyre worn close to the legal limit wearing on the inner shoulder (4.1.E.1)
Advice	N\s\f Tyre perished cracking on the outer side wall

**MOT #9**

2017-06-03 08:53

MOT test number

163051112233

Result**✗ Failed**

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)
- Advice** N\s\l Tyre perished cracking on the outer side wall
- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Pass with rectification** Nearside Headlamp aim too low (1.8)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened corroded (3.5.1i)
- Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Center brake light not working
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Advice** N\s\r slight brake bind
- Advice** Nearside Rear Tyre worn close to the legal limit wearing on the inner shoulder (4.1.E.1)

MOT #8

2016-06-02 13:11

MOT test number

188515133212

Result**✓ Passed**

- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Child seat fitted not allowing test of adult seat belts
- Advice** O/s/r tyre scrubbing on inner edge
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** All brake discs lipped

**MOT #7** 2016-06-02 11:18**MOT test number** 548380796446**Result** ✗ Failed

- Advice** Child seat fitted not allowing test of adult seat belts
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** O/s/r tyre scrubbing on inner edge
- Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)
- Advice** All brake discs lipped
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)

MOT #6 2015-06-13 16:32**MOT test number** 966504065193**Result** ✓ Passed

- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** O/s/r tyre cracking on tread area

MOT #5 2015-06-13 10:03**MOT test number** 866924165155**Result** ✗ Failed

- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** O/s/r tyre cracking on tread area
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #4** 2014-06-20 16:49**MOT test number** 968021674184**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Nsr tyre is cracking on sidewall**MOT #3** 2014-06-20 11:06**MOT test number** 448111674145**Result** ✗ Failed**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2013-06-22 12:09**MOT test number** 396673573177**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2012-08-16 12:13**MOT test number** 226549622280**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
5 January 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	5 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2009-09-01
Last registration	2023-12-29
Complete history	See info



Registration #1	2009-09-01	16 mi
Registration #2	2012-08-16	22.217 mi
Registration #3	2013-06-22	30.302 mi
Registration #4	2014-06-20	39.865 mi
Registration #5	2014-06-20	39.865 mi
Registration #6	2015-06-13	48.391 mi
Registration #7	2015-06-13	48.391 mi
Registration #8	2016-06-02	57.415 mi
Registration #9	2016-06-02	57.415 mi
Registration #10	2017-06-03	69.128 mi
Registration #11	2017-06-06	69.184 mi
Registration #12	2018-05-30	79.389 mi
Registration #13	2019-05-29	89.594 mi
Registration #14	2019-05-29	89.594 mi
Registration #15	2019-05-29	89.594 mi
Registration #16	2019-05-29	89.594 mi
Registration #17	2019-05-29	89.594 mi
Registration #18	2019-05-29	89.594 mi
Registration #19	2019-05-29	89.594 mi
Registration #20	2019-05-29	89.594 mi
Registration #21	2019-05-29	89.594 mi
Registration #22	2019-05-29	89.594 mi
Registration #23	2019-05-29	89.594 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1695 mm
Height	1470 mm
Length	3990 mm
Wheel base	2500 mm
Kerb weight	1221 kg
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FA8H366442