





report date: 2024-03-28

## General information

Make	HYUNDAI
Model	1800 CRDI SE NAV
Colour	Black
Year of manufacture	2019
Top speed	104 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	134 BHP
Max. torque	343 Nm at 1.500 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption combined	31.7 mpg
CO2 emission	222 g/km



CarCheck.co.uk page 1/11



### Internet history

#### Entry 3

Date	2021-12-28
Pictures	0

Listing price <u>View report</u>

source: heycar.co.uk

#### Entry 2

, -		
Date	2021-12-27	
Pictures	22	
Listing price	<u>View report</u>	









source: autotrader.co.uk

#### Entry 1

Date	2021-12-01
Pictures	0
Listing price	View report

source: heycar.co.uk

CarCheck.co.uk page 2/11



# MOT history

MOT expiry date	2025-02-22
MOT pass rate	50 %
MOT passed	3
Failed MOT tests	3
Total advice items	7
Total items failed	7

MOT #6	2024-02-23 12:52
MOT test number	739220444319
Result	✓ Passed
Next expiry date	2025-02-22

MOT #5	2024-02-22 13:22
MOT test number	902132300516
Result	<b>X</b> Failed
Minor  (b) (i))  Nearside Registration plate lamp inoperative in the case of multiple lamps or light (b) (i))	ght sources (4.7.1
Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice Park brake travel	
Fail Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))	

MOT #4		2023-02-02 14:35
MOT test	number	550082335539
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/11



**MOT** #3 2023-01-09 15:05 516831991872 **MOT** test number Result × Failed Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii)) Rear Tyre worn close to legal limit/worn on edge n/s & o/s (5.2.3 (e)) **Advice** Fail Windscreen washer not working (3.5 (a)) Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii)) **Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail

 MOT #2
 2021-11-29 13:35

 MOT test number
 722173070663

 Result
 ✓ Passed

 MOT #1
 2021-11-26 10:37

 MOT test number
 824827090019

 Result
 X Failed

 Fail
 Headlamp not working on dipped beam o/s and n/s/f (4.1.1 (a) (ii))

CarCheck.co.uk page 4/11



## Tax & MOT check



Tax status	Valid until 1 March
Days left	307
MOT expiry date	22 February 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	K
First licence fee (12 months)	£ 1.565,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 2.220,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



## Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full	
2000000	
***************************************	
************	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	NK NK
Plate since	
	More info

CarCheck.co.uk page 8/11



### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
011.1.6.	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



# Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2019-04-16
Last registration	2024-02-23
Complete history	See info



Registration #1	2019-04-16	26 mi
Registration #2	2021-11-26	16.795 mi
Registration #3	2021-11-29	16.799 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		T1.777 es

More info >

CarCheck.co.uk page 10/11



## Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	79%
Children	80%
Pedestrian	71%
Safety systems	56%
Overall rating	73%
Video	see crash video



# Dimensions & weight

Width	1920 mm
Height	1925 mm
Length	5150 mm
Max. allowed weight	3070 kg

### Additional information

Number of seats	8
Number of axles	2
Engine number	D4CBK812049

CarCheck.co.uk page 11/11