






report date: 2024-03-29

General information

Make	SMART	
Model	FORTWO COUPE PASSION 71	
Colour	Black	
Year of manufacture	2008	
Top speed	90 mph	
0 - 100 km/h	13.3 seconds	
0 - 60 mph	13.3 seconds	
Gearbox	5 speed Semi-Automatic	

Engine & fuel consumption

Power	52 kW / 71 HP / 71 BHP
Max. torque	92 Nm at 4.500 rpm
Engine capacity	999 сс
Cylinders	3
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	112 g/km
CO2 label	С



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2021-07-02

Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-05-09
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	16
Total items failed	10

MOT #18	2023-05-01 14:39
MOT test number	209815144570
Result	✓ Passed
Next expiry date	2024-05-09

MOT #17	2023-05-01 09:42
MOT test number	643262552476
Result	X Failed
Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #16		2022-05-10 14:13
MOT test	number	726652715483
Result		✓ Passed
Advice	Under trays fitted	
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Engine cover fitted	

CarCheck.co.uk page 3/13



Advice

Engine cover fitted

SL58FMZ

report date: 2024-03-29

MOT test number

642098641628

Result

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

Advice Under trays fitted

Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

MOT #14

MOT test number

808951355406

Result

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Under trays fitted

MOT #13 2021-07-05 11:55 **MOT** test number 180309465190 Result × Failed Fail Nearside Front Position lamp not working (4.2.1 (a) (ii)) Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) **Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) **Advice** Under trays fitted Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii)) Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

 MOT #12
 2020-07-20 15:26

 MOT test number
 750463656275

 Result
 ✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #11

MOT test number

658301061466

Result

Advice Rear Brake pipe corroded, covered in grease or other material Both (1.1.11 (c))

MOT #10

MOT test number

Result

Advice

Oil leak gearbox

Advice

Offside Rear Brake pipe slightly corroded (3.6.B.2c)

 MOT #9
 2017-05-05 11:15

 MOT test number
 328459434413

 Result
 ✓ Passed

 MOT #8
 2017-05-05 08:15

 MOT test number
 823582767981

 Result
 X Failed

Nearside Front coil spring broken (2.4.C.1a)

MOT #7

2016-05-13 09:54

MOT test number 403860836958

Result Passed

Nesure V 1 d33cd

MOT #6 2015-09-11 11:01

MOT test number 455448558079

Result ✓ Passed

Advice Nail in offside rear tyre

CarCheck.co.uk page 5/13



report date: 2024-03-29

Passed

MOT #5

MOT test number

Result

Notice Blades smearing

Notice Under-trays fitted obscuring some underside components

MOT #4 2013-09-18 12:32

MOT test number 879151563225

Result ✓ Passed

MOT #3 2012-10-01 14:49
MOT test number 485065872274

Result ✓ Passed

MOT #2 2012-10-01 14:49

MOT test number 516015772295

Result X Failed

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification Nearside Front Windscreen wiper does not clear the windscreen effectively

(8.2.2)

Result

MOT #1 2011-09-29 16:23
MOT test number 229502771214

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	9 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this SMART. See if, where and when this SMART had damage and the car repair costs. We also check if this SMART was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra SMART salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this SMART in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

More info >

Owner history For how long did the current and previous owner(s) have this SMART? How many owners did this SMART have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this SMART had different number plates. door of plates faste since

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this SMART is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SMART has been settled.

If not, and you buy this SMART then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SMART is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-10-07
Last registration	2023-05-01
Complete history	See info



Registration #1	2008-10-07	20 mi
Registration #2	2011-09-29	15.333 mi
Registration #3	2012-10-01	21.490 mi
Registration #4	2013-09-18	29.592 mi
Registration #5	2014-09-26	36.667 mi
Registration #6	2015-09-11	46.093 mi
Registration #7	2016-05-13	48.178 mi
Registration #8	2017-05-05	53.547 mi
Registration #9	2017-05-05	53.549 mi
Registration #10	2018-05-04	58.684 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1559 mm
Height	1542 mm
Length	2695 mm
Wheel base	1867 mm
Kerb weight	725 kg
Max. allowed weight	1020 kg

Additional information

Fuel tank capacity	33
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	3B21BD4139

CarCheck.co.uk page 13/13