





General information

| Make | CITROEN |
|---------------------|---------------------------------------|
| Model | DISPATCH 1000 L1H1 ENTERPRISE P/V HDI |
| Colour | White |
| Year of manufacture | 2016 |
| Top speed | 90 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 89 BHP |
|-------------------------|---------------------|
| Max. torque | 180 Nm at 1.500 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 35.8 mpg |
| Consumption extra urban | 45.6 mpg |
| Consumption combined | 42.2 mpg |
| CO2 emission | 177 g/km |
| CO2 label | I |





Internet history

Entry 1

Date Pictures 2021-11-23

27

Listing price

View report



source: cargurus.co.uk



MOT history

| MOT expiry date | 2024-09-06 |
|--------------------|------------|
| MOT pass rate | 63 % |
| MOT passed | 5 |
| Failed MOT tests | 3 |
| Total advice items | 13 |
| Total items failed | 1 |

| MOT #8 | 2023-08-11 09:24 |
|------------------|------------------|
| MOT test number | 504517488008 |
| Result | ✓ Passed |
| Next expiry date | 2024-09-06 |

| MOT #7 | | 2023-08-10 16:05 |
|----------|---|------------------|
| MOT test | number | 387692010880 |
| Result | | 🗙 Failed |
| MAJOR | Offside Front Position lamp not working (4.2.1 (a) (ii)) | |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 | (a) (ii)) |
| MAJOR | Central Stop lamp(s) not working (4.3.1 (a) (ii)) | |
| Advice | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| MAJOR | Registration plate lamp inoperative in the case of a single lamp or all lamps | (4.7.1 (b) (ii)) |
| Advice | Front Brake $pad(s)$ wearing thin (1.1.13 (a) (ii)) | |

| MOT #6 | | 2022-08-19 13:19 |
|-----------------------|---|----------------------|
| MOT test | number | 886586941784 |
| Result | | ✓ Passed |
| Minor (b) (i)) | Nearside Registration plate lamp inoperative in the case of multiple lamps or | light sources (4.7.1 |
| Advice | Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |





| MOT test number680173363744Result< Failed | MOT #F | | |
|---|----------|---|-------------------------|
| Result ★ Pailed MAJOR Exhaust system insecure (6.1.2 (a)) Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i)) MOT #4 2021-09-06 10:58 MOT test number 2021-09-06 10:58 MOT test number 2020-09-03 13:25 MOT test number 2020-09-03 13:25 MOT test number 2020-09-03 13:25 MOT test number 2019-09-07 10:59 MOT test number 2019-09-07 10:59 MOT test number 530530693127 Result Passed MOT test number S30530693127 MOT test number S30530693127 MOT test number S30530693127 MOT test number S30530693127 MOT test number S30530693127 | MOT #5 | number | 2022-08-19 10:59 |
| MAJOR Exhaust system insecure (6.1.2 (a)) Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i)) MOT #4 2021-09-06 10:58 MOT test number 907294329157 Result < Passed MOT #3 2020-09-03 13:25 MOT test number 404642537524 Result Passed MOT #2 2019-09-07 10:59 MOT test number 530530693127 Result Passed MOT #1 2019-09-07 10:59 MOT test number 530530693127 Result Passed | | number | |
| Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i)) MOT #4 2021-09-06 10:58 MOT #4 2021-09-06 10:58 MOT #4 907294329157 Result < Passed MOT #3 2020-09-03 13:25 MOT test number 404642537524 Result < Passed MOT #2 2019-09-07 10:59 MOT test number 530530693127 Result < Passed Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) MOT #1 2019-09-07 10:59 MOT #1 2019-09-07 10:59 | Result | | × Falled |
| (b) (i)) Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i)) MOT #4 2021-09-06 10:58 MOT test number 907294329157 Result ✓ Passed MOT #3 2020-09-03 13:25 MOT test number 404642537524 Result ✓ Passed MOT #2 2019-09-07 10:59 MOT test number 530530693127 Result ✓ Passed MOT #2 2019-09-07 10:59 MOT test number 530530693127 Result ✓ Passed MOT #1 2019-09-07 10:59 MOT #1 2019-09-07 10:59 MOT #1 2019-09-07 10:59 | MAJOR | Exhaust system insecure (6.1.2 (a)) | |
| MOT #4 2021-09-06 10:58 MOT test number 907294329157 Result ✓ Passed MOT #3 2020-09-03 13:25 MOT test number 404642537524 Result ✓ Passed MOT #2 2019-09-07 10:59 MOT test number 530530693127 Result ✓ Passed MOT test number 530530693127 MOT test number S0100000000000000000000000000000000000 | | Nearside Registration plate lamp inoperative in the case of multiple lamps of | or light sources (4.7.1 |
| MOT test number907294329157ResultImage: PassedMOT #32020-09-03 13:25MOT test number404642537524ResultImage: PassedMOT #22019-09-07 10:59MOT test number530530693127ResultImage: PassedMOT test numberS30530693127ResultImage: PassedMOT test numberS30530693127ResultImage: PassedMOT #12019-09-07 10:59MOT test numberS08576205105 | Advice | Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| ResultPassedMOT #32020-09-03 13:25MOT test number404642537524Result404642537524MOT #22019-09-07 10:59MOT test number530530693127Result\$98530693127Result\$98530693127Result\$98530693127MOT test number\$30530693127Result\$98530693127MOT #1\$2019-09-07 10:59MOT test number\$08576205105 | MOT #4 | | 2021-09-06 10:58 |
| MOT #3 2020-09-03 13:25 MOT test number 404642537524 Result • Passed MOT #2 2019-09-07 10:59 MOT test number 530530693127 Result • Passed MOT test number 53053053125 | MOT test | number | 907294329157 |
| MOT test number404642537524Result✓ PassedMOT #22019-09-07 10:59MOT test number530530693127Result✓ PassedAdviceFront Brake pad(s) wearing thin (1.1.13 (a) (ii))MOT #12019-09-07 10:59MOT test number508576205105 | Result | | ✓ Passed |
| MOT test number404642537524Result✓ PassedMOT #22019-09-07 10:59MOT test number530530693127Result✓ PassedAdviceFront Brake pad(s) wearing thin (1.1.13 (a) (ii))MOT #12019-09-07 10:59MOT test number508576205105 | | | |
| Result Image: Passed MOT #2 2019-09-07 10:59 MOT test number 530530693127 Result Image: Passed Image: Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) MOT #1 2019-09-07 10:59 MOT test number 508576205105 | MOT #3 | | 2020-09-03 13:25 |
| MOT #2 2019-09-07 10:59 MOT test number 530530693127 Result Image: Passed Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) MOT #1 2019-09-07 10:59 MOT test number 508576205105 | MOT test | number | 404642537524 |
| MOT test number 530530693127 Result Passed Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) MOT #1 2019-09-07 10:59 MOT test number 508576205105 | Result | | ✓ Passed |
| Result Passed Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) MOT #1 2019-09-07 10:59 MOT test number 508576205105 | MOT #2 | | 2019-09-07 10:59 |
| Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) MOT #1 2019-09-07 10:59 MOT test number 508576205105 | MOT test | number | 530530693127 |
| MOT #1 2019-09-07 10:59 MOT test number 508576205105 | Result | | ✓ Passed |
| MOT test number 508576205105 | Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| MOT test number 508576205105 | MOT #1 | | |
| | | number - | |
| Kesuit X Failed | | number | |
| | Kesult | | × Failed |

Pass with rectificationCentral Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))



Tax & MOT check

| Tax due: | ✓ MOT Expires: 6 September 2024 |
|----------------------------|--|
| 1 November 2024 Tax status | 6 September 2024 Valid until 1 November |
| Days left | 185 |
| MOT expiry date | 6 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 39 |
|---------------------------|------------|
| Standard rate (12 months) | £ 275,00,- |
| Standard rate (6 months) | £ 151,25,- |





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | | |
|----------|---------|-------|
| Date | | |
| Category | | Lamp |
| Туре | | |
| Damage 2 | | AMPL |
| Date | | · · · |
| Category | 1000000 | AMPL |
| Туре | | |

Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| xxxxxxxx | |
|--|-------------|
| ************ | |
| ******** | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this CITROEN had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Carrent registration | |
| Plate since | |
| | More info > |





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 10 |
| First mileage registration | 2016-06-30 |
| Last registration | 2023-08-11 |
| Complete history | <u>See info</u> |



| Registration #1 | 2016-06-30 | 15 mi |
|------------------|------------|------------|
| Registration #2 | 2019-09-07 | 22.904 mi |
| Registration #3 | 2019-09-07 | 22.904 mi |
| Registration #4 | 2020-09-03 | 36.542 mi |
| Registration #5 | 2021-09-06 | 46.774 mi |
| Registration #6 | | 11.177 esi |
| Registration #7 | | 11.177 mi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 esi |

More info >



Dimensions & weight

| Width | 1895 mm |
|---------------------|---------|
| Height | 1942 mm |
| Length | 4805 mm |
| Wheel base | 3000 mm |
| Kerb weight | 1673 kg |
| Max. allowed weight | 2661 kg |

Additional information

| Fuel tank capacity | 80 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of seats | 3 |
| Number of axles | 2 |
| Engine number | JBDF0091001 |