





report date: 2024-03-28

General information

Make	MINI
Model	FIRST
Colour	White
Year of manufacture	2012
Top speed	109 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	140 Nm at 2.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	127 g/km
CO2 label	D



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-09-02

Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2024-08-28
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	15
Total items failed	8

MOT #12	2023-08-29 12:55
MOT test number	103250230365
Result	✓ Passed
Next expiry date	2024-08-28
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #11	2023-08-22 13:48
MOT test number	597218965389
Result	× Failed
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Fail Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))	

MOT #10		2022-08-22 15:59
MOT test i	number	476985816116
Result		✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened x 2 (1.1.	14 (a) (ii))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #9 2022-06-14 12:39

MOT test number 775712621251

Result X Failed

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened x 2 (1.1.14 (a) (ii))

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened x 2 (1.1.14 (a) (ii))

Fail Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))

MOT #8 2021-06-30 15:51

MOT test number 454880510892

Result \(\sqrt{Passed} \)

MOT #7 2020-07-02 09:45

MOT test number 173931922504

Result Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6 2019-07-09 17:01

MOT test number 966838567431

Result

Passed

MOT #5 2018-11-27 15:57

MOT test number 540416404796

Result \rightarrow Passed

Minor Brake warning device malfunctioning or defective (1.1.4 (a) (i))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #4 2018-11-26 17:44 **MOT** test number 494251116300 Result × Failed Fail Offside Front Position lamp not working (4.2.1 (a)) Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Minor Brake warning device malfunctioning or defective (1.1.4 (a) (i)) Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii)) Fail Fail Offside Front Headlamp aim too low (4.1.2 (a)) Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #3

MOT test number

633362984932

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

 MOT #2
 2016-10-26 12:27

 MOT test number
 629403444158

 Result
 ✓ Passed

MOT #1

MOT test number

340690120481

Result

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	28 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner	history
OWITEL	HISLULY

For how long did the current and previous owner(s) have this MINI? How many owners did check it in the premium report and see all owner registrations. Download the full report		??
ARRESTS .		

THE STREET STREE		
THE STATE OF THE S		

	More info	>
Plate changes		
See in this check if this MINI had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-10-17
Last registration	2023-08-29
Complete history	See info



Registration #1	2012-10-17	14 mi
Registration #2	2015-10-15	29.961 mi
Registration #3	2016-10-26	42.784 mi
Registration #4	2017-10-14	60.334 mi
Registration #5	2018-11-26	79.964 mi
Registration #6	2018-11-27	80.008 mi
Registration #7	2019-07-09	89.568 mi
Registration #8		10.777 es
_		
Registration #9		11.777 mi
Registration #9 Registration #10		11.777 es
		11.777 es 11.777 es
Registration #10		11.777 es
Registration #10 Registration #11		11,777 es 11,777 es 11,777 es 11,777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1060 kg
Max. allowed weight	1520 kg

Additional information

Fuel tank capacity	40
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles2Engine numberA516J341