





report date: 2024-03-28

General information

Make	BMW
Model	Z4 Z4 SDRIVE20I M SPORT ROADSTER
Colour	Black
Year of manufacture	2015
Top speed	144 mph
0 - 60 mph	6.9 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	184 BHP
Max. torque	270 Nm at 4.500 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	53.3 mpg
Consumption combined	41.5 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/12



Internet history

Entry 3

Date 2021-10-23

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 2

Date	2021-10-03
Pictures	0
Listing price	View report

source: heycar.co.uk

Entry 1

Date 2021-08-25

Pictures 22

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-02-21
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	23
Total items failed	2

MOT #7		2024-02-22 16:06
MOT test	number	548511161787
Result		✓ Passed
Next expiry date 2025-02-		2025-02-21
Advice Nearside Rear Inner Stop lamp(s) non-obligatory stop lamp not working inop (4.3.1 (a) (ii))		
Advice	Nearside Rear Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #6		2023-02-09 12:25
MOT test	number	808931635832
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.1	.1 (c))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)) (ii))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11	(c))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 3/12



MOT #5 2023-02-08 14:22

MOT test number 391097991529

Result × Failed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Minor Nearside Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

MOT #4 2020-10-15 12:31

MOT test number 264889115787

Result \(\sqrt{Passed} \)

MOT #3 2019-06-13 12:14

MOT test number 616100979665

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))

CarCheck.co.uk page 4/12



MOT #2 2019-05-30 10:53

MOT test number 728982210980

Result

× Failed

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))

Fail

Offside Rear Road wheel fractured (5.2.2 (a))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge 255/35/18 2mm (5.2.3 (e))

Advice

Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement

front bush (5.3.4 (a) (i))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge 255/35/18 2mm (5.2.3 (e))

MOT #1 2018-06-12 10:04

MOT test number 592009927980

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 August
Days left	95
MOT expiry date	21 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



,	
For how long did the current and previous owner(s) have this BMW? How many owners defect it in the premium report and see all owner registrations. Download the full report	

manuse .	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-06-08
Last registration	2024-02-22
Complete history	See info



Registration #1	2015-06-08	28 mi
Registration #2	2018-06-12	29.178 mi
Registration #3	2019-05-30	39.917 mi
Registration #4	2019-06-13	40.188 mi
Registration #5	2020-10-15	47.175 mi
Registration #6		71.777 66
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		9.77 ss
Registration #10		11.777 66
Registration #11		0.777-46

More info >

CarCheck.co.uk page 11/12



Car features

50225	Air conditionin
50295	
60482	
60501	
0566	
0567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1790 mm
Height	1291 mm
Length	4239 mm
Wheel base	2496 mm
Kerb weight	1420 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats CarCheck.co.uk	2 page 12/