





report date: 2024-03-28

## General information

Make	FIAT
Model	PUNTO GBT
Colour	White
Year of manufacture	2012
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 сс
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E



CarCheck.co.uk page 1/14



report date: 2024-03-28

## Internet history

### Entry 2

Date	2023-04-07
Pictures	0
Listing price	View report

#### source: cargurus.co.uk

#### Entry 1

Date	2021-07-18	
Pictures	64	
Listing price	<u>View report</u>	









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MK12EYW report date: 2024-03-28

MOT history

MOT expiry date	2024-05-18
MOT pass rate	56 %
MOT passed	9
Failed MOT tests	7
Total advice items	18
Total items failed	26

MOT #16	2023-04-19 16:41
MOT test number	268467813805
Result	✓ Passed
Next expiry date	2024-05-18

MOT #15	2023-04-17 15:12
MOT test number	166731974769
Result	<b>X</b> Failed
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Fail Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))	
Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	

MOT #14	2022-04-22 11:34
MOT test number	189009174351
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/14



report date: 2024-03-28

**MOT #13** 2022-04-20 10:22

**MOT test number** 920075082393

Result X Failed

Fail Exhaust carbon monoxide content at idle exceeds manufacturer's specified limits (8.2.1.2 (b))

Fail Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))

MOT #12 2021-05-19 16:16

MOT test number 186133828301

**Result** 
✓ Passed

**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #11** 2021-05-18 16:04

MOT test number 481735142276

**Result** X Failed

**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #10** 2020-05-08 13:03

MOT test number 742379163750

Advice Rear Exhaust mounting defective exhaust back box outer sleeve is deteriorated but still functioning as intended (6.1.2 (a))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

CarCheck.co.uk page 4/14



report date: 2024-03-28

2020-05-08 09:28 **MOT #9** 141520850734 **MOT** test number Result × Failed Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Fail Nearside Front Brake rod has restricted free movement calliper (1.1.15 (e)) Advice Oil leak, but not excessive (8.4.1 (a) (i)) Fail Nearside Front Position lamp not working (4.2.1 (a) (ii)) Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) **Advice** Rear Exhaust mounting defective exhaust back box outer sleeve is deteriorated but still functioning as intended (6.1.2 (a)) Fail Nearside Front Direction indicator not working (4.4.1 (a) (ii))

MOT #8	2019-03-29 17:05
MOT test number	360827418292
Result	✓ Passed
MOT #7	2018-03-30 10:21
MOT test number	789236157347
Result	✓ Passed
Advice Oil leak	
Advice Front Bumper insecure	

CarCheck.co.uk page 5/14



report date: 2024-03-28

**MOT** #6 2018-03-29 10:25 725429766673 **MOT** test number Result × Failed **Advice** Oil leak Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail Exhaust emissions hydrocarbon content after 2nd fast idle excessive (7.3.D.3) Front Brake pad(s) less than 1.5 mm thick (3.5.1g) Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2) Fail **Advice** Front Bumper insecure Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4) Fail **Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3) Fail Rear Registration plate lamp not working (1.1.C.1d)

MOT #5		2017-03-28 09:23
MOT test	number	845653230589
Result		<b>✓</b> Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #4	2016-03-24 16:41
MOT test number	842134600909
Result	<b>✓</b> Passed

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT test number

324954452866

Result

Fail Offside Rear Stop lamp not working (1.2.1b)

Fail Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail Offside Front Headlamp not working on dipped beam (1.7.5a)

Fail Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #2

MOT test number

755656085056

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT test number

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Windscreen washer provides insufficient washer liquid (8.2.3)

CarCheck.co.uk page 7/14



report date: 2024-03-28

## Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	18 May 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

## Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

# Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report <u>I</u>	
HARMAN CONTRACTOR CONT	
***************************************	
*******	
***************************************	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-28

### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



MK12EYW report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2012-03-29
Last registration	2023-04-19
Complete history	See info



Registration #1	2012-03-29	27 mi
Registration #2	2015-03-27	25.597 mi
Registration #3	2015-03-27	25.598 mi
Registration #4	2016-03-24	38.274 mi
Registration #5	2016-03-24	38.274 mi
Registration #6	2017-03-28	51.709 mi
Registration #7	2018-03-29	67.628 mi
Registration #8	2018-03-30	67.631 mi
Registration #9	2019-03-29	81.929 mi
Registration #10	2020-05-08	95.187 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		D.777 es
Registration #19		10.777 es

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1585 kg

# Additional information

Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles Carcheck.co.uk	2 page 14/14