





report date: 2024-03-28

General information

Make	MAZDA
Model	MX-5 I
Colour	Red
Year of manufacture	2007
Top speed	122 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	167 Nm at 4.500 rpm
Engine capacity	1.798 сс
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.7 mpg
CO2 emission	174 g/km
CO2 label	Н



CarCheck.co.uk page 1/12



report date: 2024-03-28


Internet history

Entry 1

Date 2021-06-05

Pictures 38

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2024-06-14
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	2
Total items failed	3

MOT #17	2023-05-26 08:45
MOT test number	792698140231
Result	✓ Passed
Next expiry date	2024-06-14

MOT #16	2022-05-17 15:57
MOT test number	749693354145
Result	✓ Passed

MOT #15	2022-05-17 09:00
MOT test number	448146586183
Result	X Failed
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #14	2021-06-15 13:08
MOT test number	493176651787
Result	✓ Passed

MOT #13	2021-06-11 12:46
MOT test number	773315153959
Result	× Failed
Fail Offside Front Anti-roll bar linkage insecurely attached (5.3.3 (a) (i))	

CarCheck.co.uk page 3/12



Advice

GV57HME

report date: 2024-03-28

MOT #12	2020-09-22 10:30	
MOT test number	962176703278	
Result	✓ Passed	
MOT #11	2019-09-05 07:45	
MOT test number	251768348440	
Result	✓ Passed	
MOT #10	2018-09-06 09:51	
MOT test number	854678244958	
Result	✓ Passed	
Advice Nearside Front Service brake binding but not excessively (1.2.1 (f))		
MOT #9	2018-09-05 10:59	
MOT test number	545251984528	
Result	X Failed	
Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))		

MOT #8	2017-09-06 13:00
MOT test number	363691391869
Result	✓ Passed
MOT #7	2016-08-23 12:16
MOT test number	326368275635
Result	✓ Passed
MOT #6	2015-08-24 15:29
MOT test number	910639130103
Result	✓ Passed

Nearside Front Service brake binding but not excessively (1.2.1 (f))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5 2014-09-16 13:26

MOT test number 966619854242

Result ✓ Passed

MOT #4 2013-08-27 15:00

MOT test number 438429133201

Result

Passed

MOT #3 2012-08-28 10:22

MOT test number 235441742264

Result ✓ Passed

MOT #2 2011-08-23 13:57

MOT test number 409295331237

MOT #1 2010-09-09 11:00

MOT test number 853092050257

Result ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	14 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



GV57HME report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

\sim		ner	11-15		
-(-)	w/r	۱er	nı	СТ	nrν
\sim	V V I				\mathbf{v}

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full research		PΑ

	More info	>
Plate changes		
See in this check if this MAZDA had different number plates.		
Number of plates		
Current registration	UK NE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-09-22
Last registration	2023-05-26
Complete history	See info



Registration #1	2007-09-22	20 mi
Registration #2	2010-09-09	14.994 mi
Registration #3	2011-08-23	17.723 mi
Registration #4	2012-08-28	20.835 mi
Registration #5	2013-08-27	24.924 mi
Registration #6	2014-09-16	28.602 mi
Registration #7	2015-08-24	32.436 mi
Registration #8	2016-08-23	37.654 mi
Registration #9	2017-09-06	40.802 mi
Registration #10	2018-09-05	43.327 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		
Registration #10		

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1720 mm
Height	1245 mm
Length	3995 mm
Wheel base	2330 mm
Kerb weight	1065 kg
Max. allowed weight	1365 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	L8 20203447

CarCheck.co.uk page 12/12