



report date: 2024-03-29

General information

Make	FORD
Model	FIESTA SPORT TDCI
Colour	White
Year of manufacture	2017
Gearbox	5 speed Manual

Engine & fuel consumption

Power	94 BHP
Engine capacity	1.499 cc
Cylinders	4
Fuel type	Diesel
Consumption city	65.7 mpg
Consumption extra urban	88.3 mpg
Consumption combined	78.5 mpg
CO2 emission	94 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-06-04
Pictures	22
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2024-07-26
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	6
Total items failed	9

MOT #8	2023-07-27 18:36
MOT test number	859463741607
Result	✓ Passed
Next expiry date	2024-07-26

MOT #7	2023-07-20 15:31
MOT test number	308818284073
Result	✗ Failed
Fail	Offside Rear Road wheel fixing missing (5.2.1 (a) (i))
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))
Fail	Offside Rear Rear fog lamp does not emit a steady red light (4.5.4 (a))
Fail	Exhaust on a vehicle fitted with a diesel particulate filter emits visible smoke of any colour (8.2.2.2 (d))
Fail	Offside Rear fog lamp likely to become detached (4.5.1 (c) (ii))

MOT #6	2022-06-06 15:39
MOT test number	406116197733
Result	✓ Passed
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Engine cover & undertray fitted

**MOT #5** 2022-06-06 14:10**MOT test number** 421852506870**Result** ✗ Failed**Advice** Engine cover & undertray fitted**Fail** Offside Rear fog lamp does not emit a steady red light (4.5.4 (a))**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure out of shape (5.2.3 (d) (ii))**Minor** Offside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**MOT #4** 2021-05-21 10:03**MOT test number** 991259953512**Result** ✓ Passed**MOT #3** 2021-05-20 13:00**MOT test number** 875927280123**Result** ✗ Failed**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #2** 2020-12-03 11:57**MOT test number** 889252799588**Result** ✓ Passed**MOT #1** 2020-05-23 09:06**MOT test number** 852737800464**Result** ✓ Passed**Advice** COVID-19 6 MONTH EXTENSION



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-05-31
Last registration	2023-07-27
Complete history	See info



Registration #1	2017-05-31	6 mi
Registration #2	2020-12-03	75.559 mi
Registration #3	2021-05-20	78.401 mi
Registration #4	2021-05-21	78.401 mi
Registration #5	2023-07-27	78.401 mi
Registration #6	2023-07-27	78.401 mi
Registration #7	2023-07-27	78.401 mi
Registration #8	2023-07-27	78.401 mi
Registration #9	2023-07-27	78.401 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	86%
Pedestrian	65%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1978 mm
Height	1433 mm
Length	3982 mm
Kerb weight	1070 kg
Max. allowed weight	1565 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	GA89432