



report date: 2024-03-28

General information

Make	CITROEN
Model	C1 PURETECH FLAIR
Colour	White
Year of manufacture	2017
Top speed	106 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	82 BHP
Max. torque	116 Nm at 2.750 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	52.3 mpg
Consumption extra urban	76.4 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 6



Date	2021-02-17
Pictures	15
Listing price	View report



source: yesauto.com

Entry 5




Date	2021-02-06
Pictures	19
Listing price	View report



source: yesauto.com

Entry 4

Date	2021-02-01
Pictures	19
Listing price	View report







source: yesauto.com

Entry 3

Date	2021-01-31
Pictures	19

Listing price

[View report](#)







source: yesauto.com

Entry 2

Date 2021-01-30

Pictures 19

Listing price [View report](#)





source: yesauto.com

Entry 1

Date 2021-01-22

Pictures 20

Listing price [View report](#)



source: yesauto.com

**MOT history**

MOT expiry date	2025-02-23
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	0
Total items failed	4

MOT #7	2024-02-16 12:25
MOT test number	740874042521
Result	✓ Passed
Next expiry date	2025-02-23

MOT #6	2023-02-01 15:37
MOT test number	653860491130
Result	✓ Passed

MOT #5	2023-02-01 11:02
MOT test number	883148897965
Result	✗ Failed
Fail Nearside Front Tyre has a tear, caused by separation or partial failure of its structure outer sidewall exposing cords (5.2.3 (d) (ii))	
Fail Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure outer sidewall exposing cords (5.2.3 (d) (ii))	
Fail Offside Rear Tyre has a tear, caused by separation or partial failure of its structure outer sidewall exposing cords (5.2.3 (d) (ii))	

MOT #4	2022-02-04 14:13
MOT test number	443406455685
Result	✓ Passed



MOT #3	2022-02-03 16:45
MOT test number	250016373780
Result	✗ Failed
<div><div>Fail</div>Nearside Front Inner Tyre has a bulge, caused by separation or partial failure of its structure sidewall (5.2.3 (d) (ii))</div>	

MOT #2	2021-02-24 12:53
MOT test number	121114168908
Result	✓ Passed

MOT #1	2020-01-20 11:12
MOT test number	685851965621
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
23 February 2025

Tax status	Valid until 1 April
Days left	338
MOT expiry date	23 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	PG66XFX
Plate since	2024-03-28
Current registration	PG66XFX
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2017-01-31
Last registration	2024-02-16
Complete history	See info



Registration #1	2017-01-31	8 mi
Registration #2	2020-01-20	8.633 mi
Registration #3	2020-01-20	20,277 mi
Registration #4	2020-01-20	20,277 mi
Registration #5	2020-01-20	20,277 mi
Registration #6	2020-01-20	20,277 mi
Registration #7	2020-01-20	20,277 mi
Registration #8	2020-01-20	20,277 mi
Registration #9	2020-01-20	20,277 mi
Registration #10	2020-01-20	20,277 mi
Registration #11	2020-01-20	20,277 mi
Registration #12	2020-01-20	20,277 mi
Registration #13	2020-01-20	20,277 mi
Registration #14	2020-01-20	20,277 mi

More info >



Safety ratings

NCAP rating	★★★★
Adult	68%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	66%
Video	see crash video



Dimensions & weight

Width	1615 mm
Height	1460 mm
Length	3465 mm
Wheel base	2340 mm
Kerb weight	865 kg
Max. allowed weight	1240 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	B2220059738