





report date: 2024-03-28

General information

Make	AUDI
Model	TT ROADSTER 150
Colour	Blue
Year of manufacture	2004
Top speed	133 mph
0 - 60 mph	8.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	210 Nm at 1.750 rpm
Engine capacity	1.781 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	43.5 mpg
Consumption combined	34.0 mpg
CO2 emission	197 g/km
CO2 label	J



CarCheck.co.uk page 1/16



report date: 2024-03-28

Internet history

Entry 1

Date 2021-01-28

Pictures 8

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/16



report date: 2024-03-28

N/I	α		uc:	t۸	r\/
101	•		115	w	ıv
	•	Γh			. ,

MOT expiry date	2025-04-03
MOT pass rate	77 %
MOT passed	17
Failed MOT tests	5
Total advice items	57
Total items failed	9

MOT #22		2024-04-04 11:31
MOT test	number	288857940142
Result		✓ Passed
Next expi	ry date	2025-04-03
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.	1.11 (c))
Advice	Exhaust coroded	
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice (5.3.4 (a) (Offside Front Lower Suspension arm pin or bush worn but not resulting in extin)	xcessive movement
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Advice	Rear axle coroded	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.	11 (c))
Advice (5.3.4 (a) (Nearside Front Lower Suspension arm pin or bush worn but not resulting in (i))	excessive movement
Advice	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	

CarCheck.co.uk page 3/16



report date: 2024-03-28

MOT #21 2023-03-31 10:39

MOT test number 254007302382

Result ✓ Passed

Advice Rear axle coroded

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #20 2022-01-06 15:05

MOT test number 567234096509

Result ✓ Passed

Advice Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

MOT #19 2020-12-29 13:10

MOT test number 271644659237

CarCheck.co.uk page 4/16



report date: 2024-03-28

MOT #18 2020-05-09 14:06

MOT test number 908736243600

MOT #17 2019-05-17 10:38

MOT test number 613653264833

Result

Passed

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Front Oil leak, but not excessive from engine (8.4.1 (a) (i))

MOT #16 2019-05-16 15:27

MOT test number 930935358942

Result X Failed

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

Advice Front Oil leak, but not excessive from engine (8.4.1 (a) (i))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

CarCheck.co.uk page 5/16



report date: 2024-03-28

MOT #15 2018-05-19 08:21

MOT test number 614105903328

Result ✓ Passed

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)

Advice Rear tyres worn in central tread

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive

movement (2.4.G.2)

Advice Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)

Advice Front tyres worn on inner edges

MOT #14 2016-11-18 10:24

MOT test number 390519923111

Result
✓ Passed

Advice Tyre worn close to the legal limit both rear (4.1.E.1)

MOT #13 2015-12-18 11:35

MOT test number 737169192481

Advice Engine management lamp is on indicating an engine fault

CarCheck.co.uk page 6/16



report date: 2024-03-28

MOT #12 2015-12-16 10:44 **MOT** test number 759180392053 Result × Failed **Advice** Front Brake discs are corroded Fail Offside Brake pad(s) less than 1.5 mm thick (3.5.1g) Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) **Advice** Engine management lamp is on indicating an engine fault Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail Nearside Front coil spring broken (2.4.C.1a)

MOT #11

MOT test number

767990664163

Result

Advice (2.4.G.2)

Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement

MOT #10

MOT test number

818224563175

Result

Notice Exhaust centre hanger broken but still supports exhaust

2013-06-13 09:30

818224563175

MOT test number

Result

Advice Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Offside Registration plate lamp not working (1.1.C.1d)

Advice Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 7/16



report date: 2024-03-28

MOT test number

Result

Advice Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Tyre worn close to the legal limit (4.1.E.1)

MOT #7

MOT test number

Result

MOT test number

Result

MOT #6

MOT test number

317075821152

Result

Pass with rectification

Nearside Front Front position lamp(s) not working (1.1.A.3b)

MOT #5		2010-03-19 12:01
MOT test	number	362418570064
Result		✓ Passed
Advice	Windscreen has damage to an area less than a 40mm circle outside zon	e 'A' (8.3.1d)
Notice	Nearside rear tyre perished	
Notice	Damage to nearside front bumper/wing	
Advice (2.4.G.2)	Offside Front Suspension arm rubber bush deteriorated but not resulting	g in excessive movement

CarCheck.co.uk page 8/16



report date: 2024-03-28

MOT #4 2010-03-12 18:31 **MOT test number** 890451470022 Result × Failed Fail Offside Rear coil spring incomplete (2.4.C.1a) Notice Damage to nearside front bumper/wing **Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2) Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d) Notice Nearside rear tyre perished

MOT #3		2009-03-11 11:15
MOT test	number	100470879002
Result		✓ Passed
Advice	Nearside Power steering pipe(s) or hose(s) has slight seepage (2.3.3b)	
Notice	Both rear tyres slightly perished	
Advice (2.4.G.2)	Offside Front Suspension arm rubber bush deteriorated but not resulting in	n excessive movement

MOT #2	2008-03-14 13:00
MOT test number	130524278046
Result	✓ Passed
MOT #1	2007-03-05 15:16
MOT test number	331184367099
Result	✓ Passed

CarCheck.co.uk page 9/16



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	3 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 10/16



report date: 2024-03-28

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/16



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 12/16



report date: 2024-03-28

O١			- La 2	
- () (Λ/n	ıer	n	

For how long did the current and previous owner(s) have this AUDI? How many owners did check it in the premium report and see all owner registrations. Download the full report		/e?
THE PARTY OF THE P		

	More info	>
Plate changes		
See in this check if this AUDI had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 13/16



report date: 2024-03-28

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 14/16



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2004-03-01
Last registration	2024-04-04
Complete history	See info



Registration #1	2004-03-01	20 mi
Registration #2	2007-03-05	23.861 mi
Registration #3	2008-03-14	33.439 mi
Registration #4	2009-03-11	39.928 mi
Registration #5	2010-03-12	41.899 mi
Registration #6	2010-03-19	41.912 mi
Registration #7	2011-05-05	46.796 mi
Registration #8	2012-07-06	56.646 mi
Registration #9	2013-06-13	64.643 mi
Registration #10	2014-06-09	75.883 mi
Registration #11	2015-12-16	94.755 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		n.m 44

More info >

CarCheck.co.uk page 15/16



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
50566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1856 mm
Height	1348 mm
Length	4041 mm
Wheel base	2429 mm
Kerb weight	1335 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number CarCheck.co.uk	AUM 108315 page 16/16