



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE TSI
Colour	Black
Year of manufacture	2015
Top speed	111 mph
0 - 100 km/h	10.9 seconds
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	77 kW / 105 HP / 103 BHP
Max. torque	175 Nm at 1.500 rpm
Engine capacity	1.197 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	137 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2024-04-19
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	10
Total items failed	0

MOT #8	2023-04-20 15:30
MOT test number	131042456075
Result	✓ Passed
Next expiry date	2024-04-19
Advice	Nearside Front Suspension component pin or bush slightly worn REAR WISHBONE ARM BUSH (5.3.4 (a) (i))
Advice	Offside Front Suspension component pin or bush slightly worn REAR WISHBONE ARM BUSH (5.3.4 (a) (i))

MOT #7	2023-03-06 10:05
MOT test number	640579711381
Result	✗ Failed
MAJOR	Rear Rear fog lamp not working (4.5.1 (a) (ii))

MOT #6	2022-03-25 11:30
MOT test number	501375081756
Result	✓ Passed
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #5	2021-03-23 12:35
MOT test number	230911221678
Result	✓ Passed

**MOT #4** 2021-03-22 16:54**MOT test number** 919457278361**Result** ✗ Failed**DANGEROUS** Nearside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**DANGEROUS** Offside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**MOT #3** 2020-03-10 17:08**MOT test number** 216724674087**Result** ✓ Passed**MOT #2** 2019-03-22 13:31**MOT test number** 407407868679**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened both rear (1.1.14 (a) (ii))**Advice** Brake pad(s) wearing thin both rear (1.1.13 (a) (ii))**MOT #1** 2018-03-08 08:40**MOT test number** 255230195123**Result** ✓ Passed**Advice** Under trays fitted



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✗  
**MOT**  
**Expired:**  
19 April 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	19 April 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>SK15XGU</b>
Plate since	2015-05-29
Current registration	<b>SK15XGU</b>
Plate since	2015-05-29

More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-03-31
Last registration	2023-04-20
Complete history	<a href="#">See info</a>



Registration #1	2015-03-31	21 mi
Registration #2	2018-03-08	32.085 mi
Registration #3	2019-03-22	41.738 mi
Registration #4	2020-03-10	50.890 mi
Registration #5	2020-03-20	51.277 mi
Registration #6	2020-03-20	51.277 mi
Registration #7	2020-03-20	51.277 mi
Registration #8	2020-03-20	51.277 mi
Registration #9	2020-03-20	51.277 mi
Registration #10	2020-03-20	51.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	90%
Pedestrian	53%
Safety systems	86%
Overall rating	83%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2021 mm
Height	1486 mm
Length	4278 mm
Wheel base	2537 mm
Kerb weight	1274 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	CBZBH25596