



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO E (55BHP)
Colour	Red
Year of manufacture	2007
Top speed	94 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg
CO2 emission	138 g/km
CO2 label	E





## MOT history

MOT expiry date	2024-12-20
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	44
Total items failed	7

MOT #18 2023-12-20 10:13

MOT test number 502689220307

Result ✓ Passed

Next expiry date 2024-12-20

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #17 2022-12-05 16:58

MOT test number 640148228281

Result ✓ Passed

- Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #16** 2021-12-10 17:43**MOT test number** 624238802607**Result** ✓ Passed**MOT #15** 2020-12-21 11:40**MOT test number** 157263917496**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Advice** Brake slack adjuster advise adjustment (1.1.18 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge Worn to the limit. 1.6mm (5.2.3 (e))

**MOT #14** 2020-12-17 11:42**MOT test number** 153600686223**Result** ✗ Failed

- MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Brake slack adjuster advise adjustment (1.1.18 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge Worn to the limit. 1.6mm (5.2.3 (e))
- MAJOR** Nearside Side repeater lens defective such that the emitted light is adversely affected (4.4.1 (b) (ii))

**MOT #13** 2019-11-14 12:07**MOT test number** 769411574536**Result** ✓ Passed**MOT #12** 2019-11-13 15:48**MOT test number** 745574091804**Result** ✗ Failed

**MAJOR** Offside Front Lower Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MAJOR** Offside Rear Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #11** 2018-12-10 16:17**MOT test number** 517621763590**Result** ✓ Passed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10** 2017-12-07 17:59**MOT test number** 453783981512**Result** ✓ Passed**MOT #9** 2016-12-12 13:47**MOT test number** 672244232680**Result** ✓ Passed

**MOT #8** 2016-12-09 15:43**MOT test number** 407686207413**Result** ✗ Failed**Fail** Nearside Front Inner Suspension arm has excessive play in a pin/bush rear bush (2.4.G.2)**Fail** Offside Front Inner Suspension arm has excessive play in a pin/bush rear bush (2.4.G.2)**MOT #7** 2015-11-17 08:43**MOT test number** 425068173123**Result** ✓ Passed**Advice** Horn tone poor**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear fog lamp slightly discoloured (1.3.2e)**MOT #6** 2014-12-17 16:58**MOT test number** 316231554396**Result** ✓ Passed**Advice** Offside Side repeater obscured but not more than 50% (1.4.A.2d)**Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**Advice** Offside Rear fog lamp slightly discoloured (1.3.2e)

**MOT #5**

2014-12-16 09:55

**MOT test number**

498140554381

**Result****✗ Failed**

- Advice** Offside Rear fog lamp slightly discoloured (1.3.2e)
- Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)
- Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)
- Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Offside Side repeater obscured but not more than 50% (1.4.A.2d)
- Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
- Fail** Front Exhaust has a major leak of exhaust gases (7.1.2)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Notice** Both front brake binding slightly.
- Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)

**MOT #4**

2013-12-07 12:09

**MOT test number**

985971243349

**Result****✓ Passed**

- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)

**MOT #3**

2012-12-13 15:03

**MOT test number**

889358142392

**Result****✓ Passed**

- Advice** Offside Rear fog lamp slightly discoloured (1.3.2e)
- Notice** Child seat fitted not allowing full inspection of adult belt



MOT #2	2011-11-19 10:07
MOT test number	326173321316
Result	✓ Passed
MOT #1	2010-12-14 11:24
MOT test number	612588340324
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
20 December 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	33
<b>MOT expiry date</b>	20 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-29
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-06-28
Last registration	2023-12-20
Complete history	<a href="#">See info</a>



Registration #1	2007-06-28	14 mi
Registration #2	2010-12-14	21.945 mi
Registration #3	2011-11-19	30.229 mi
Registration #4	2012-12-13	39.913 mi
Registration #5	2013-12-07	48.669 mi
Registration #6	2014-12-16	57.893 mi
Registration #7	2014-12-17	57.893 mi
Registration #8	2015-11-17	62.788 mi
Registration #9	2016-12-09	64.001 mi
Registration #10	2016-12-12	64.001 mi
Registration #11	2016-12-12	64.001 mi
Registration #12	2016-12-12	64.001 mi
Registration #13	2016-12-12	64.001 mi
Registration #14	2016-12-12	64.001 mi
Registration #15	2016-12-12	64.001 mi
Registration #16	2016-12-12	64.001 mi
Registration #17	2016-12-12	64.001 mi
Registration #18	2016-12-12	64.001 mi
Registration #19	2016-12-12	64.001 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Kerb weight	1186 kg
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	BMD194531