





report date: 2024-03-30

General information

Make	VOLKSWAGEN
Model	CC MATCH TDI BLUEMOTION TECHNOLOGY
Colour	White
Year of manufacture	2015
Top speed	123 mph
0 - 100 km/h	9.8 seconds
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 kW / 150 HP / 148 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	56.5 mpg
CO2 emission	130 g/km
CO2 label	D



CarCheck.co.uk page 1/11



Internet history

Entry 1


Date 2021-08-10

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



B 4	\sim $-$			
10.71	α	- h	sto	rv
101	() I		510	II V
	•		-	. ,

MOT expiry date	2025-03-13
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	8
Total items failed	1

MOT #8	2024-03-14 11:40
MOT test number	748794705845
Result	✓ Passed
Next expiry date	2025-03-13

MOT #7	2023-03-13 13:05
MOT test number	373832496683
Result	✓ Passed

MOT #6		2022-03-11 13:14
MOT test	number	766675620281
Result		✓ Passed
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

CarCheck.co.uk page 3/11



KX65NHK

report date: 2024-03-30

MOT #5 2021-03-05 13:25

MOT test number 891738131771

Result ✓ Passed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #4 2020-03-05 16:50

MOT test number 616113527433

MOT #3 2020-03-05 10:39

MOT test number 138269788835

Result X Failed

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Inner edge (5.2.3 (d) (i))

MOT #2 2019-03-12 16:31

MOT test number 286387586937

Result

Passed

MOT #1 2018-08-30 08:03

MOT test number 389128982723

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	13 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date

Category


Damage 2

Category

Type

Date

Туре



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



KX65NHK

report date: 2024-03-30

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Downere.	

THE STREET STREET	
Plate changes	More info >
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Combact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-09-01
Last registration	2024-03-14
Complete history	See info



Registration #1	2015-09-01	25 mi
Registration #2	2018-08-30	20.511 mi
Registration #3	2019-03-12	23.712 mi
Registration #4	2020-03-05	34.714 mi
Registration #5	2020-03-05	34.714 mi
Registration #6		11.777 es
Registration #7		11.777 es
Designation #0		
Registration #8		
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	87%
Children	79%
Pedestrian	48%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	2041 mm
Height	1703 mm
Length	4426 mm
Wheel base	2604 mm
Kerb weight	1597 kg
Max. allowed weight	2150 kg

Additional information

Fuel tank capacity	64 I
Fuel delivery	Direct Injection
Number of doors	5
CarChack so uk	nago 11/11

CarCheck.co.uk page 11/11

Number of seats	5
Number of axles	2
Engine number	CUVC429980