



SPIOWA

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	FOX
Colour	Grey
Year of manufacture	-
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg



**MOT history**

<b>MOT #15</b>	2020-11-04 12:28
<b>MOT test number</b>	686265577899
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2021-11-06
<b>Minor</b>	Offside Headlamp lens slightly defective (4.1.1 (b) (i))

<b>MOT #14</b>	2020-11-02 12:35
<b>MOT test number</b>	518744537174
<b>Result</b>	✗ Failed
<b>DANGEROUS</b>	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
<b>MAJOR</b>	Front Exhaust has a major leak of exhaust gases front pipe in poor condition (6.1.2 (a))
<b>MAJOR</b>	Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
<b>Minor</b>	Offside Headlamp lens slightly defective (4.1.1 (b) (i))
<b>MAJOR</b>	Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

<b>MOT #13</b>	2019-11-04 09:29
<b>MOT test number</b>	964553720984
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))
<b>Advice</b>	Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))
<b>Advice</b>	Offside Front Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #12**

2019-11-04 09:29

**MOT test number**

731903158698

**Result****✗ Failed****Pass with rectification**

Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**Advice**

Offside Front Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**Advice**

Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

**Advice**

Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

**MOT #11**

2018-11-07 12:24

**MOT test number**

207364196794

**Result****✓ Passed****Minor**

Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice**

Nearside Front Upper Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

**MOT #10**

2017-10-30 14:07

**MOT test number**

561675534114

**Result****✓ Passed****MOT #9**

2017-10-27 08:02

**MOT test number**

476276216304

**Result****✗ Failed****Advice**

Exhaust system deteriorated

**Fail**

Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

**Advice**

Front Exhaust has a minor leak of exhaust gases flexi (7.1.2)

**Fail**

Nearside Front Suspension arm has excessive play in a pin/bush (2.4.G.2)

**MOT #8** 2016-10-28 10:03**MOT test number** 531873078574**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit uneven wear (4.1.E.1)**Advice** Front Exhaust has a minor leak of exhaust gases pipe at flexi end joint (7.1.2)**MOT #7** 2016-10-27 09:06**MOT test number** 166580793320**Result** ✗ Failed**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Fail** Offside Front coil spring broken (2.4.C.1a)**Fail** Front Windscreen wiper does not clear the windscreen effectively both sides torn&smearing (8.2.2)**Advice** Front Exhaust has a minor leak of exhaust gases pipe at flexi end joint (7.1.2)**Advice** Offside Front Tyre worn close to the legal limit uneven wear (4.1.E.1)**MOT #6** 2015-10-31 09:58**MOT test number** 113425873116**Result** ✓ Passed**MOT #5** 2014-11-06 16:46**MOT test number** 166160114301**Result** ✓ Passed**Notice** Nearside rear brake sticking**MOT #4** 2013-11-07 14:38**MOT test number** 799651213362**Result** ✓ Passed



MOT #3	2013-11-06 17:15
MOT test number	666050013308
Result	✗ Failed
Fail	Fuel system component leaking (7.2.3)

MOT #2	2013-03-22 09:32
MOT test number	928521983038
Result	✓ Passed

MOT #1	2013-03-21 13:17
MOT test number	615360883015
Result	✗ Failed
Fail	Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-03-25
Last registration	2020-11-04
Complete history	<a href="#">See info</a>



Registration #1	2010-03-25	23 mi
Registration #2	2013-03-21	28.448 mi
Registration #3	2013-03-22	28.448 mi
Registration #4	2013-11-06	32.534 mi
Registration #5	2013-11-07	32.534 mi
Registration #6	2014-11-06	36.494 mi
Registration #7	2015-10-31	39.403 mi
Registration #8	2016-10-27	42.020 mi
Registration #9	2016-10-27	42.020 mi
Registration #10	2016-10-27	42.020 mi
Registration #11	2016-10-27	42.020 mi
Registration #12	2016-10-27	42.020 mi
Registration #13	2016-10-27	42.020 mi
Registration #14	2016-10-27	42.020 mi
Registration #15	2016-10-27	42.020 mi
Registration #16	2016-10-27	42.020 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

<b>Number of seats</b>	4
<b>Number of axles</b>	2
<b>Engine number</b>	CHF 058721