





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO S
Colour	Black
Year of manufacture	2007
Top speed	104 mph
0 - 60 mph	13.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.390 сс
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.8 mpg
CO2 emission	165 g/km
CO2 label	G



CarCheck.co.uk page 1/14



·

Internet history

Entry 2

Date 2021-02-06

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-12-28
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	15
Total items failed	9

MOT #18		2023-12-15 11:07
MOT test	number	755712199453
Result		✓ Passed
Next expi	ry date	2024-12-28
Advice	Advice Axle swivel pins and bushes swivel pin and/or bush slightly worn o/s/r & n/s/r (5.1.2 (b) (i))	
Advice	Advice Brake disc worn, pitted or scored, but not seriously weakened o/s/f & n/s/f (1.1.14 (a) (ii))	
Advice Direction indicator slightly discoloured o/s/r & n/s/r (4.4.3 (a))		
Advice	Advice Exhaust system corroded & start distorting front to rear	
Advice	Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))	

CarCheck.co.uk page 3/14



MOT #17 2023-12-13 10:43

MOT test number 631484496731

Result X Failed

Fail Nearside Front Headlamp aim too low (4.1.2 (a))

Advice Exhaust system corroded & start distorting front to rear

Advice Axle swivel pins and bushes swivel pin and/or bush slightly worn o/s/r & n/s/r (5.1.2 (b) (i))

Fail Offside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))

Advice Brake disc worn, pitted or scored, but not seriously weakened o/s/f & n/s/f (1.1.14 (a) (ii))

Advice Direction indicator slightly discoloured o/s/r & n/s/r (4.4.3 (a))

Advice Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #16 2022-12-12 13:27

MOT test number 107634310463

Result \(\sqrt{Passed} \)

Advice Central Front Exhaust has a minor leak of exhaust gases joint area. (6.1.2 (a))

MOT #15 2022-12-09 11:59

MOT test number 159917792022

Result X Failed

Fail Offside Rear Service brake excessively binding (1.2.1 (f))

Fail Brakes imbalanced across an axle by more than 50% front brakes (1.2.1 (b) (ii))

Fail Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4

Fail Front Brakes imbalanced across an axle Axle 1 (1.2.1 (b) (i))

(b) (ii))

CarCheck.co.uk page 4/14



MOT #14 2021-12-15 09:56

MOT test number 432669102742

Result \rightarrow Passed

Advice

Front Oil leak, but not excessive (8.4.1 (a) (i))

MOT #13 2020-12-29 18:00

MOT test number 875094316670

Result ✓ Passed

MOT #12 2019-12-06 14:32

MOT test number 746046991291

Result \rightarrow Passed

Minor Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #11 2019-12-05 11:54

MOT test number 757670030450

Result X Failed

Minor Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Fail Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))

Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

MOT #10 2018-12-10 12:02

MOT test number 974841103250

MOT #9 2017-10-25 11:48

MOT test number 887753205861

Result

Passed

CarCheck.co.uk page 5/14



BT57RVV

report date: 2024-03-29

MOT test number 440498042690

Result ✓ Passed

MOT #7 2015-10-19 15:04

MOT test number 111099772605

Result

Passed

MOT #6 2014-10-24 08:35

MOT test number 149257294290

Result
✓ Passed

MOT #5 2013-10-28 12:01

MOT test number 469921403323

Result ✓ Passed

MOT #4 2012-11-13 12:21

MOT test number 516758312390

Result ✓ Passed

MOT #3 2012-10-30 14:57

MOT test number 899564802308

Result X Failed

Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2011-11-21 12:49

MOT test number 725175521377

CarCheck.co.uk page 6/14



BT57RVV

report date: 2024-03-29

MOT #1 2010-11-29 09:56

MOT test number 254963730306

Result ✓ Passed

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	28 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date

Category

Type

Damage 2
Date

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many volkswagen have? Check it in the premium report and see all owner registrations. Dow here.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



BT57RVV

report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-12-01
Last registration	2023-12-15
Complete history	See info



Registration #1	2007-12-01	20 mi
Registration #2	2010-11-29	20.097 mi
Registration #3	2011-11-21	24.705 mi
Registration #4	2012-10-30	29.913 mi
Registration #5	2012-11-13	30.084 mi
Registration #6	2013-10-28	35.373 mi
Registration #7	2014-10-24	41.089 mi
Registration #8	2015-10-19	46.363 mi
Registration #9	2016-11-25	51.333 mi
Registration #10	2017-10-25	53.126 mi
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		9.70 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		n.m.

More info >

CarCheck.co.uk page 13/14



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.	
S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	

View the complete VOLKSWAGEN factory list for this vehicle here.

More info >

Safety ratings

S0569

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Kerb weight	1142 kg
Max. allowed weight	1770 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
CarChack co.uk	page 14/14

CarCheck.co.uk page 14/14

Number of axles	2
Engine number	BUD 077170