



PEUGEOT



AFI3WDV


report date: 2024-03-28

General information

Make	PEUGEOT
Model	BOXER HDI 335 L3H2 P/V
Colour	White
Year of manufacture	2013
Top speed	92 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.4 mpg
Consumption extra urban	37.7 mpg
Consumption combined	32.5 mpg
CO2 emission	229 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-11-27
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-18
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	11
Total items failed	1

MOT #10	2024-01-19 08:30
MOT test number	791426321960
Result	✓ Passed
Next expiry date	2025-01-18
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9	2022-12-09 11:45
MOT test number	315547520503
Result	✓ Passed
Advice	Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Engine covers and under trays fitted obscuring view of testable components

MOT #8	2021-10-29 09:15
MOT test number	909819342575
Result	✓ Passed

MOT #7	2020-11-10 13:02
MOT test number	104785861422
Result	✓ Passed

**MOT #6** 2019-11-04 14:05**MOT test number** 909560403589**Result** ✓ Passed**MOT #5** 2018-11-05 16:12**MOT test number** 127992519281**Result** ✓ Passed**MOT #4** 2017-11-10 17:14**MOT test number** 245091520952**Result** ✓ Passed**MOT #3** 2017-04-26 14:04**MOT test number** 182449647670**Result** ✓ Passed**Advice** Leaf spring splayed but action not impaired both rear springs have little reserve travel and are permanently on bump stops. Suspect vehicle is overloaded (2.4.B.1c)**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #2** 2016-05-27 14:27**MOT test number** 285585677182**Result** ✓ Passed**Advice** Nearside wing mirror damaged**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Nearside Rear tyre outer side wall worn



MOT #1	2016-05-26 08:26
MOT test number	481368605409
Result	✗ Failed
Advice	Nearside wing mirror damaged
Fail	Offside Rear Tyre has ply or cords exposed inner side wall (4.1.D.1b)
Advice	Nearside Rear tyre outer side wall worn
Advice	Parking brake lever has little reserve travel (3.1.6b)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
18 January 2025

Tax status	Valid until 1 July
Days left	64
MOT expiry date	18 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-06-10
Last registration	2024-01-19
Complete history	See info



Registration #1	2013-06-10	7 mi
Registration #2	2016-05-26	36.542 mi
Registration #3	2016-05-27	36.549 mi
Registration #4	2017-04-26	50.387 mi
Registration #5	2017-11-10	54.906 mi
Registration #6	2018-11-05	69.138 mi
Registration #7	2019-05-29	75.277 mi
Registration #8	2019-05-29	75.277 mi
Registration #9	2019-05-29	75.277 mi
Registration #10	2019-05-29	75.277 mi
Registration #11	2019-05-29	75.277 mi
Registration #12	2019-05-29	75.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	59%
Children	86%
Pedestrian	26%
Safety systems	26%
Overall rating	54%
Video	see crash video



Dimensions & weight

Width	2508 mm
Height	2524 mm
Length	5998 mm
Kerb weight	2101 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Number of axles	2

