



MJ56XEN

report date: 2024-03-29

General information

Make	FORD
Model	FUSION ZETEC CLIMATE
Colour	Blue
Year of manufacture	-
Top speed	111 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	146 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.8 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-30
Pictures	41
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #17	2020-09-14 14:15
MOT test number	689483333159
Result	✓ Passed
Next expiry date	2021-10-05
Minor	Indicator tell-tale inoperative left (4.9.1 (a) (i))

MOT #16	2019-09-10 14:34
MOT test number	144154523272
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Front Tyre worn close to legal limit/worn on edge both fronts (5.2.3 (e))

MOT #15	2019-09-05 15:58
MOT test number	325685962631
Result	✗ Failed
Fail	Offside Front Brake pipe excessively corroded (1.1.11 (c))
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Front Tyre worn close to legal limit/worn on edge both fronts (5.2.3 (e))

**MOT #14**

2018-10-06 14:22

MOT test number

153610892711

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #13

2018-10-06 10:52

MOT test number

925940399796

Result

✗ Failed

- Fail** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12** 2017-12-13 12:36**MOT test number** 339314629354**Result** ✓ Passed**Advice** Central Front Lower Items removed from driver's view prior to test**Advice** Central Front Upper Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #11** 2017-12-13 10:29**MOT test number** 194124365621**Result** ✗ Failed**Advice** Central Front Upper Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Central Front Lower Items removed from driver's view prior to test**Fail** Offside Rear Brake pipe excessively corroded (3.6.B.2c)**MOT #10** 2016-11-29 16:15**MOT test number** 508285010359**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit on 2mm (4.1.E.1)**Advice** Central Front Lower Items removed from driver's view prior to test**Advice** Nearside Front Tyre worn close to the legal limit on 2mm (4.1.E.1)

**MOT #9** 2016-11-29 12:31**MOT test number** 490760494584**Result** ✗ Failed**Fail** Nearside Rear Stop lamp not working (1.2.1b)**Advice** Nearside Front Tyre worn close to the legal limit on 2mm (4.1.E.1)**Advice** Central Front Lower Items removed from driver's view prior to test**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Offside Front Tyre worn close to the legal limit on 2mm (4.1.E.1)**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**MOT #8** 2015-12-22 10:12**MOT test number** 648119809796**Result** ✓ Passed**Advice** Offside Front Lower Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #7** 2015-12-22 10:12**MOT test number** 468996083344**Result** ✗ Failed**Pass with rectification** Centre Front Lower Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**Advice** Offside Front Lower Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #6** 2014-12-12 14:48**MOT test number** 678876344344**Result** ✓ Passed**Notice** Items removed from driver's view prior to test

**MOT #5** 2013-12-19 09:27**MOT test number** 429353753384**Result** ✓ Passed**Notice** Items removed from driver's view prior to test**MOT #4** 2012-12-20 12:01**MOT test number** 135715252339**Result** ✓ Passed**Notice** Items removed from driver's view prior to test**MOT #3** 2011-12-21 10:14**MOT test number** 609015751334**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2010-10-08 09:29**MOT test number** 410001780209**Result** ✓ Passed**MOT #1** 2009-10-19 11:50**MOT test number** 334502099476**Result** ✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	MJ56XEN
Plate since	2019-09-29
Current registration	MJ56XEN
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-12-11
Last registration	2020-09-14
Complete history	See info



Registration #1	2006-12-11	9 mi
Registration #2	2009-10-19	10.293 mi
Registration #3	2010-10-08	23.098 mi
Registration #4	2011-12-21	44.606 mi
Registration #5	2012-12-20	60.420 mi
Registration #6	2013-12-19	76.529 mi
Registration #7	2014-12-12	91.939 mi
Registration #8	2015-12-22	104.314 mi
Registration #9	2015-12-22	104.314 mi
Registration #10	2016-11-29	112.529 mi
Registration #11	2016-11-29	112.529 mi
Registration #12	2016-11-29	112.529 mi
Registration #13	2016-11-29	112.529 mi
Registration #14	2016-11-29	112.529 mi
Registration #15	2016-11-29	112.529 mi
Registration #16	2016-11-29	112.529 mi
Registration #17	2016-11-29	112.529 mi
Registration #18	2016-11-29	112.529 mi
Registration #19	2016-11-29	112.529 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1210 kg
Max. allowed weight	1605 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	6B54593