





report date: 2024-03-29

General information

Make	RENAULT	
Model	SCENIC DYNAMIQUE TOMTOM BOSE PACK DC	
Colour	Red	
Year of manufacture	2011	
Top speed	112 mph	
0 - 100 km/h	12.5 seconds	
Gearbox	6 speed Manual	

Engine & fuel consumption

Power	78 kW / 106 HP / 110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.7 mpg
CO2 emission	128 g/km
CO2 label	D



CarCheck.co.uk page 1/14



Internet history

Entry 1

Date 2021-02-04

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-11-24
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	38
Total items failed	9

MOT #15		2023-11-25 09:39
MOT test	number	714481173774
Result		✓ Passed
Next expi	ry date	2024-11-24
Advice	Engine covers under trays & sill covers are fitted thus not allowing full inspection	
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive m	novement
Advice	Offside Rear Service brake binding but not excessively	
Advice	Central Exhaust heat shield loose	
Advice Offside Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))		
Advice	Exhaust emissions are too clean to get a reading	
Advice	Nearside Rear Service brake binding but not excessively	
Advice	Central Rear Stop lamp(s) non-obligatory stop lamp not working	
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

CarCheck.co.uk page 3/14



MOT #14 2023-11-08 12:45

MOT test number 557162756024

Result X Failed

Advice Engine covers under trays & sill covers are fitted thus not allowing full inspection

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Fail Offside Rear Brakes imbalanced across an axle (1.2.1 (b) (i))

Advice Central Exhaust heat shield loose

Advice Central Rear Stop lamp(s) non-obligatory stop lamp not working

Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Exhaust emissions are too clean to get a reading

MOT #13 2023-01-17 14:53

MOT test number 525957024568

Result / Passed

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Foremost (5.3.4 (a) (i))

Advice Nearside Rear Outer Tyre worn close to legal limit/worn on edge Close to showing plys (5.2.3 (e))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

Advice Central Exhaust heat shield loose

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement

Foremost (5.3.4 (a) (i))

CarCheck.co.uk page 4/14



MOT #12 2023-01-06 08:55

MOT test number 495425679144

Result × Failed

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Fail Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

Advice Central Exhaust heat shield loose

Advice Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement

Foremost (5.3.4 (a) (i))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Fail Offside Rear Direction indicator incorrect colour (4.4.3 (a))

Advice Nearside Rear Outer Tyre worn close to legal limit/worn on edge Close to showing plys (5.2.3 (e))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement

Foremost (5.3.4 (a) (i))

MOT #11 2022-01-14 11:02

MOT test number 256936036154

Result

Passed

Advice Oil leak in the engine bay area

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Exhaust emissions are too clean to get a reading

Advice Slight play in the front suspension arms bushes

Advice Engine covers, under trays & sill covers are fitted thus not allowing full inspection

CarCheck.co.uk page 5/14



MOT #10 2021-01-16 14:36
MOT test number 752054156175

Advice

Re-issued to to retest error

MOT #9 2021-01-16 14:31

MOT test number 815014483204

Result × Failed

Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #8 2021-01-15 16:31

MOT test number 614520246763

Result X Failed

Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #7 2019-06-20 10:18

MOT test number 238835733129

Result
✓ Passed

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #6 2018-06-25 14:40

MOT test number 756781208767

Result ✓ Passed

MOT #5 2018-06-25 10:14

MOT test number 309006072663

Result × Failed

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

CarCheck.co.uk page 6/14



MOT #4	2017-04-28 10:46
MOT test number	965968547100
Result	✓ Passed
MOT #3	2016-05-13 15:52
MOT test number	431739044717
Result	✓ Passed
MOT #2	2015-04-27 13:26
MOT test number	218447015178
Result	✓ Passed
MOT #1	2014-06-26 14:37
MOT test number	417537474196
Result	✓ Passed

CarCheck.co.uk page 7/14





Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	24 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-


CarCheck.co.uk page 8/14



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner	history
OWITEL	HISLULY

,		
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full		AULT

	More info	>
Plate changes		
See in this check if this RENAULT had different number plates.		
Number of plates		
Current registration	NE UK	
Plate since		1.01.0
Current registration	NIE UK	
Plate since		1.01.0
	More info	>

CarCheck.co.uk page 11/14



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-09-09
Last registration	2023-11-25
Complete history	See info



Registration #1	2011-09-09	14 mi
Registration #2	2014-06-26	15.523 mi
Registration #3	2015-04-27	17.307 mi
Registration #4	2016-05-13	22.766 mi
Registration #5	2017-04-28	26.308 mi
Registration #6	2018-06-25	30.716 mi
Registration #7	2018-06-25	30.716 mi
Registration #8	2019-06-20	41.928 mi
Registration #9	2021-01-15	45.943 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		D.277 es

More info >

CarCheck.co.uk page 13/14



Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
S0567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1486 mm
Height	1637 mm
Length	4344 mm
Wheel base	2703 mm
Kerb weight	1385 kg
Max. allowed weight	1944 kg

Additional information

Fuel tank capacity	60 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 14/14

Number of axles 2

Engine number D246598