



report date: 2024-03-29

## General information

Make	VOLVO
Model	V50 SE LUX D S40
Colour	Grey
Year of manufacture	2008
Top speed	127 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg
CO2 emission	153 g/km
CO2 label	G








Internet history

Entry 1

Date	2022-08-07
Pictures	37
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



**MOT history**

<b>MOT expiry date</b>	2024-07-24
<b>MOT pass rate</b>	76 %
<b>MOT passed</b>	13
<b>Failed MOT tests</b>	4
<b>Total advice items</b>	18
<b>Total items failed</b>	2

<b>MOT #17</b>	2023-07-17 11:09
<b>MOT test number</b>	762522151119
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-07-24
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Advice</b>	Central exhaust corroded

<b>MOT #16</b>	2022-07-25 17:53
<b>MOT test number</b>	514853676368
<b>Result</b>	✓ Passed

<b>MOT #15</b>	2021-09-09 09:06
<b>MOT test number</b>	759985650417
<b>Result</b>	✓ Passed
<b>Advice</b>	Central Front Lower Oil leak, but not excessive (8.4.1 (a) (i))
<b>Advice</b>	Offside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))
<b>Advice</b>	Nearside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))
<b>Advice</b>	Nearside Rear OUTER CASING CORRODED ON REAR EXHAUST BOX.



**MOT #14** 2020-09-10 11:46**MOT test number** 570456823509**Result** ✓ Passed

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #13** 2019-09-11 07:41**MOT test number** 773679134384**Result** ✓ Passed

**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #12** 2019-09-10 10:29**MOT test number** 762843895439**Result** ✗ Failed

**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MAJOR** Exhaust emissions exceed manufacturer's specified limit TESTED ON PLATE LIMIT OF, 1.33.  
(8.2.2.2 (a))

**MOT #11** 2018-08-30 15:35**MOT test number** 416139745293**Result** ✓ Passed

**Advice** Child Seat fitted not allowing full inspection of adult belt

**MOT #10** 2018-08-28 11:46**MOT test number** 184042206456**Result** ✗ Failed

**Advice** Child Seat fitted not allowing full inspection of adult belt

**DANGEROUS** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))



**MOT #9** 2017-08-29 12:49**MOT test number** 582153260222**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #8** 2017-08-29 12:49**MOT test number** 940588813228**Result** ✗ Failed**Pass with rectification** Offside Rear position lamp(s) not working (1.1.A.3b)**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #7** 2016-08-24 16:42**MOT test number** 258685151238**Result** ✓ Passed**MOT #6** 2016-08-24 16:42**MOT test number** 714853885452**Result** ✗ Failed**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**MOT #5** 2016-01-26 15:48**MOT test number** 569537150135**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2015-02-06 13:07**MOT test number** 985837735094**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt





MOT #3	2014-03-19 18:21
MOT test number	927508774003
Result	✓ Passed
MOT #2	2013-04-02 10:37
MOT test number	176982993019
Result	✓ Passed
MOT #1	2011-10-12 09:10
MOT test number	966825081258
Result	✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
24 July 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	24 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-





Damage history


Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX


More info >





Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-10-16
Last registration	2023-07-17
Complete history	<a href="#">See info</a>



Registration #1	2008-10-16	28 mi
Registration #2	2011-10-12	55.581 mi
Registration #3	2013-04-02	61.980 mi
Registration #4	2014-03-19	63.372 mi
Registration #5	2015-02-06	70.424 mi
Registration #6	2016-01-26	76.133 mi
Registration #7	2016-08-24	80.080 mi
Registration #8	2016-08-24	80.080 mi
Registration #9	2017-08-29	86.458 mi
Registration #10	2017-08-29	86.458 mi
Registration #11	2018-08-29	92.836 mi
Registration #12	2019-08-29	99.214 mi
Registration #13	2020-08-29	105.592 mi
Registration #14	2021-08-29	111.970 mi
Registration #15	2022-08-29	118.348 mi
Registration #16	2023-08-29	124.726 mi
Registration #17	2024-08-29	131.104 mi
Registration #18	2025-08-29	137.482 mi
Registration #19	2026-08-29	143.860 mi

More info >





Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1457 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5



<b>Number of axles</b>	2
<b>Engine number</b>	411629