



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	GOLF S TSI
Colour	Silver
Year of manufacture	2010
Top speed	124 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	122 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	55.4 mpg
Consumption combined	45.6 mpg
CO2 emission	144 g/km
CO2 label	F






Internet history

Entry 2



Date	2021-09-08
Pictures	39
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

Entry 1

Date	2021-06-07
Pictures	36
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-24
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	27
Total items failed	8

MOT #182023-08-19 15:14

MOT test number865281419808

Result✓ Passed

Next expiry date2024-08-24

- AdviceNearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- AdviceNearside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))
- AdviceRear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- AdviceOffside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- AdviceOffside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))
- AdviceOil leak, but not excessive engine (8.4.1 (a) (i))

**MOT #17**

2023-08-19 08:33

**MOT test number**

902251619618

**Result****✗ Failed**

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))
- Fail** Rear Exhaust has a major leak of exhaust gases clamps broken (6.1.2 (a))
- Advice** Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #16**

2022-08-06 15:55

**MOT test number**

527324939088

**Result****✓ Passed**

- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #15**

2021-08-25 16:08

**MOT test number**

400645631621

**Result****✓ Passed****MOT #14**

2021-08-25 15:32

**MOT test number**

830997764858

**Result****✗ Failed**

- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))



<b>MOT #13</b>	2020-12-29 16:01
<b>MOT test number</b>	600305366476
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear Exhaust silencer heat shield insecure

<b>MOT #12</b>	2020-12-29 12:09
<b>MOT test number</b>	472729350047
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Rear Service brake excessively binding (1.2.1 (f))
<b>Fail</b>	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
<b>Fail</b>	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
<b>Fail</b>	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
<b>Advice</b>	Rear Exhaust silencer heat shield insecure

<b>MOT #11</b>	2019-12-17 10:23
<b>MOT test number</b>	221774693030
<b>Result</b>	✓ Passed
<b>Minor</b>	Offside Front Windscreen wiper blade defective (3.4 (b) (i))
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Rear exhaust heat shield insecure
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #10</b>	2018-12-28 12:56
<b>MOT test number</b>	604659041834
<b>Result</b>	✓ Passed
<b>Advice</b>	Exhaust corroded
<b>Advice</b>	Under trays fitted

**MOT #9** 2018-12-28 10:36**MOT test number** 185236613858**Result** ✗ Failed**Advice** Exhaust corroded**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Under trays fitted**MOT #8** 2018-01-02 12:37**MOT test number** 430105413683**Result** ✓ Passed**MOT #7** 2017-05-03 08:36**MOT test number** 221372035618**Result** ✓ Passed**MOT #6** 2016-04-27 08:26**MOT test number** 181418479647**Result** ✓ Passed**MOT #5** 2015-04-23 09:18**MOT test number** 995013415120**Result** ✓ Passed**MOT #4** 2014-04-24 09:43**MOT test number** 579524914123**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components

**MOT #3** 2013-05-23 09:54**MOT test number** 197873443185**Result** ✓ Passed**Notice** Off side front seat belt frayed ( slight )**MOT #2** 2013-02-12 16:41**MOT test number** 525773643022**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2013-02-12 12:45**MOT test number** 929063843068**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
24 August 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	93
<b>MOT expiry date</b>	24 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-





Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<div><div></div><div>XXXXXX</div></div>
Plate since	2020-06-29
Current registration	<div><div></div><div>XXXXXX</div></div>
Plate since	2020-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2010-01-18
Last registration	2023-08-19
Complete history	<a href="#">See info</a>



Registration #1	2010-01-18	19 mi
Registration #2	2013-02-12	34.504 mi
Registration #3	2013-02-12	34.504 mi
Registration #4	2013-05-23	35.559 mi
Registration #5	2014-04-24	45.127 mi
Registration #6	2015-04-23	54.204 mi
Registration #7	2016-04-27	64.184 mi
Registration #8	2017-05-03	76.229 mi
Registration #9	2018-01-02	82.976 mi
Registration #10	2018-12-28	86.843 mi
Registration #11	2018-12-28	86.843 mi
Registration #12	2019-01-01	86.843 mi
Registration #13	2019-01-01	86.843 mi
Registration #14	2019-01-01	86.843 mi
Registration #15	2019-01-01	86.843 mi
Registration #16	2019-01-01	86.843 mi
Registration #17	2019-01-01	86.843 mi
Registration #18	2019-01-01	86.843 mi
Registration #19	2019-01-01	86.843 mi
Registration #20	2019-01-01	86.843 mi
Registration #21	2019-01-01	86.843 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1786 mm
Height	1479 mm
Length	4199 mm
Wheel base	2578 mm
Kerb weight	1215 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	CAX 539598