





General information

Make	VOLVO
Model	C30 D3 SE LUX
Colour	Silver
Year of manufacture	2012
Top speed	127 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 1.500 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry	1
Date	

Pictures

2022-04-15

27

Listing price

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-14
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	10
Total items failed	2

MOT #10	2023-05-15 15:57
MOT test number	765547078724
Result	✓ Passed
Next expiry date	2024-05-14

МОТ #9	2022-04-12 13:26
MOT test number	766858068468
Result	✓ Passed

MOT #8	B 2022-04-11 10:33
MOT te	st number 625490219370
Result	× Failed
Fail	Offside Front Lower Suspension arm pin or bush excessively worn rear mount (5.3.4 (a) (i))
Fail	Nearside Front Tyre(s) of different sizes are fitted on the same axle. space saver spare (5.2.3 (b))





MOT #7	2021-11-15 14:47
MOT test number	924636824987
Result	✓ Passed
Advice Offside Rear Lower Suspension arm pin or bush worn but not resulting in exercise (5.3.4 (a) (i))	cessive movement
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice Nearside Rear Lower Suspension arm pin or bush worn but not resulting in e (5.3.4 (a) (i))	xcessive movement
Minor (b) (i)) Nearside Registration plate lamp inoperative in the case of multiple lamps or	light sources (4.7.1
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive (i))	e movement (5.3.4 (a)

MOT #6		2020-11-17 16:36
MOT test	number	647688563212
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #5	2019-12-03 16:45
MOT test number	297390468648
Result	✓ Passed
Advice Nearside Front Outer Tyre slightly damaged wall cut (5.2.3 (d) (ii))	

MOT #4	2018-12-04 11:36
MOT test number	686319458013
Result	✓ Passed
MOT #3	2017-12-04 13:38
MOT test number	607923424922

MOT test number

🗸 Passed



YX62	PPF
report date:	2024-03-28

MOT #2	2016-12-07 14:50
MOT test number	904174419087
Result	✓ Passed
MOT #1	2015-08-10 10:09
MOT test number	678112225286
Result	✓ Passed
Notice Both front tyres inner edges starting to wear to bald	



Tax & MOT check

✓ Taxed Tax due: 1 September 2024	✓ MOT Expires: 14 May 2024
Tax status	Valid until 1 September
Days left	125
MOT expiry date	14 May 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	4. ARMPE
Туре	
Damage 2	AMPL
	F Stores
Date	1.E
Category	ante
Туре	

Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

ana	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-09-05
Last registration	2023-05-15
Complete history	See info



Registration #1	2012-09-05	11 mi
Registration #2	2015-08-10	24.532 mi
Registration #3	2016-12-07	27.681 mi
Registration #4	2017-12-04	30.553 mi
Registration #5	2018-12-04	33.683 mi
Registration #6	2019-12-03	36.258 mi
_		
Registration #7		11.777 est
Registration #7 Registration #8		20.222 est
-		01,000 est 01,000 est 01,000 est
Registration #8		01,000 est 01,000 est 01,000 est 01,000 est
Registration #8 Registration #9		01,000 est 01,000 est 01,000 est 01,000 est 01,000 est

More info >





Car features

S0225	Air conditioning
\$0295	
50482	
S0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating	****
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight	
Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1471 kg
Max. allowed weight	1900 kg
Additional information	
Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles	2
Engine number	1200407