





report date: 2024-03-28

General information

| Make | MAZDA |
|---------------------|----------------|
| Model | 2 TAMURA |
| Colour | Black |
| Year of manufacture | - |
| Top speed | 107 mph |
| 0 - 60 mph | 12.9 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 85 BHP |
|-------------------------|---------------------|
| Max. torque | 122 Nm at 3.500 rpm |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 40.9 mpg |
| Consumption extra urban | 67.3 mpg |
| Consumption combined | 54.3 mpg |



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history


Entry 1

Date 2021-06-13

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT test number
707438176960

Result
Passed

Next expiry date
Advice
Nearside Front Inner Play in steering rack inner joint(s)

Advice
Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Minor
Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT test number
701764036796

Result

Advice Nearside Front Inner Play in steering rack inner joint(s)

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Minor Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Pass with rectification Front Windscreen washer provides insufficient washer liquid (3.5 (a))

| MOT #13 | 2021-04-17 09:32 |
|-----------------|------------------|
| MOT test number | 284108690107 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #12 2021-04-14 13:03 894720506340 **MOT** test number Result × Failed Fail Nearside Side repeater not working (4.4.1 (a) (ii)) Fail Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii)) **Advice** Offside Front Outer Track rod end ball joint has slight play (2.1.3 (b) (i)) Nearside Headlamp aim too low (4.1.2 (a)) Fail Fail Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii)) Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Fail

MOT #11

MOT test number

484634748062

Result

Advice Radiator insecure

MOT #10 2020-03-24 15:41 **MOT** test number 351524068879 Result × Failed Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) **Advice** Radiator insecure Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Fail Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

 MOT #9
 2019-03-28 14:10

 MOT test number
 461380927248

 Result
 ✓ Passed

CarCheck.co.uk page 4/12



Fail

MK10VCM

report date: 2024-03-28

MOT #8

MOT test number

484547096405

Result

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Fail Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MOT #7 2018-04-16 10:01 **MOT** test number 446787801557 Result ✓ Passed **Advice** Front Lower Valance Damaged and Temporary Repair Made To Mountings **Advice** Nearside Steering rack gaiter deteriorated (2.2.D.2d) Advice Nearside Front Inner Road wheel with a slightly distorted bead rim (4.2.A.1a) Advice Steering column universal joint has slight play (2.1.5) **Advice** Radiator Mountings Damaged and Temporary Repair made **Advice** Front Bumper insecure **Advice** Offside Steering rack gaiter deteriorated (2.2.D.2d) **Advice** Offside Play in steering rack inner joint(s)

MOT #6 2017-04-29 12:08

MOT test number 609923909944

Result ✓ Passed

MOT #5

MOT test number

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 5/12



MK10VCM report date: 2024-03-28

MOT #4 2015-04-29 09:12

MOT test number 528769615199

MOT #3 2014-05-02 08:58

MOT test number 156032224113

Result ✓ Passed

MOT #2 2014-05-02 08:58

MOT test number 489722924111

Result X Failed

Pass with rectification Nearside Front position lamp(s) not working (1.1.A.3b)

MOT #1 2013-05-03 17:40

MOT test number 519913023173

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

| For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively. | |
|---|---|
| | |
| | |
| | |
| | |
| *************************************** | |
| *************************************** | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this MAZDA had different number plates. | |
| Number of plates | , |
| Current registration | AIR SIE |
| Plate since | |
| Current registration | NIE |
| Plate since | |
| | More info > |

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 10/12



MK10VCM report date: 2024-03-28

Mileage check

Registration #16

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 16 |
| First mileage registration | 2010-03-31 |
| Last registration | 2022-05-11 |
| Complete history | See info |



| Registration #1 | 2010-03-31 | 23 mi |
|------------------|------------|-----------|
| Registration #2 | 2013-05-03 | 31.207 mi |
| Registration #3 | 2014-05-02 | 36.718 mi |
| Registration #4 | 2015-04-29 | 44.361 mi |
| Registration #5 | 2016-05-06 | 50.266 mi |
| Registration #6 | 2017-04-29 | 54.369 mi |
| Registration #7 | 2018-04-16 | 63.094 mi |
| Registration #8 | 2019-03-28 | 70.967 mi |
| Registration #9 | | 11.177 es |
| Registration #10 | | 11.177 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | 77,777 46 |
| Registration #13 | | 11.177 es |
| Registration #14 | | 0.00 44 |
| Registration #15 | | 11.177 mi |
| | | |

PRIN. 20. 20

More info >

71.777 mi

CarCheck.co.uk page 11/12



MK10VCM report date: 2024-03-28

Safety ratings

| NCAP rating | **** |
|-------------|------|
|-------------|------|

Video <u>see crash video</u>



Dimensions & weight

| Width | 1695 mm |
|---------------------|---------|
| Height | 1475 mm |
| Length | 3895 mm |
| Wheel base | 2490 mm |
| Kerb weight | 1030 kg |
| Max. allowed weight | 1485 kg |

Additional information

| Fuel tank capacity | 42 I |
|--------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | ZJ 803747 |

CarCheck.co.uk page 12/12