



report date: 2024-03-29

General information

Make	VAUXHALL
Model	AGILA S
Colour	Silver
Year of manufacture	2011
Top speed	109 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	118 Nm at 4.800 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 2

Date	2022-01-20
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Date	2022-01-18
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-15
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	17
Total items failed	2

MOT #13	2024-02-19 09:47
MOT test number	456582767202
Result	✓ Passed
Next expiry date	2025-03-15
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #12	2023-02-22 12:55
MOT test number	854863555629
Result	✓ Passed

MOT #11	2023-02-16 11:57
MOT test number	167490148309
Result	✗ Failed
MAJOR	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #10	2022-03-16 12:49
MOT test number	997601429900
Result	✓ Passed

**MOT #9** 2021-09-21 08:29**MOT test number** 515013544208**Result** ✓ Passed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2.5mm (5.2.3 (e))**Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**MOT #8** 2020-09-17 09:34**MOT test number** 202662097284**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Brake pipe corroded, covered in grease or other material Front To Rear At Rear (1.1.11 (c))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Wishbone Rear Bush (5.3.4 (a) (i))**Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated Leaking Around Clip (6.1.7 (g) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #7** 2019-09-19 08:36**MOT test number** 639636291498**Result** ✓ Passed**MOT #6** 2018-09-20 11:02**MOT test number** 152815528331**Result** ✓ Passed**Minor** Offside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2017-09-15 09:47**MOT test number** 943060093741**Result** ✓ Passed**Advice** Offside Front Suspension arm has slight play in a ball joint bottom ball joint (2.4.G.2)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement bottom arm rear bush (2.4.G.2)**Advice** Nearside Rear Nail in tyre**MOT #4** 2016-09-06 09:01**MOT test number** 906032927738**Result** ✓ Passed**MOT #3** 2016-09-05 10:02**MOT test number** 174002905103**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Pass with rectification** Nearside Headlamp aim too high (1.8)**MOT #2** 2015-09-01 08:58**MOT test number** 993582711771**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened BOTH (3.5.1i)**MOT #1** 2014-09-01 09:23**MOT test number** 499534944205**Result** ✓ Passed**Notice** Nearside front tyre on 3mil



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
15 March 2025

Tax status	Valid until 1 March
Days left	305
MOT expiry date	15 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	FX61YRG
Plate since	2019-06-29
Current registration	FX61YRG
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-09-27
Last registration	2024-02-19
Complete history	See info



Registration #1	2011-09-27	10 mi
Registration #2	2014-09-01	17.455 mi
Registration #3	2015-09-01	22.111 mi
Registration #4	2016-09-05	27.856 mi
Registration #5	2016-09-06	27.856 mi
Registration #6	2017-09-15	38.597 mi
Registration #7	2018-09-20	50.350 mi
Registration #8	2019-09-19	62.722 mi
Registration #9	2020-09-20	75.117 mi
Registration #10	2021-09-20	87.512 mi
Registration #11	2022-09-20	100.000 mi
Registration #12	2023-09-20	112.488 mi
Registration #13	2024-02-19	125.000 mi
Registration #14	2024-02-19	137.512 mi
Registration #15	2024-02-19	150.000 mi
Registration #16	2024-02-19	162.512 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	990 kg
Max. allowed weight	1485 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	1331429