




report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D DRIVE S
Colour	Silver
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	108 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-12-10
Pictures	10
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-12-06
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	30
Total items failed	11

MOT #17 2022-11-07 16:49

MOT test number 764483924139

Result ✓ Passed

Next expiry date 2023-12-06

- Advice** Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16 2021-12-07 16:16

MOT test number 770085590908

Result ✓ Passed

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #15**

2021-12-07 15:17

MOT test number

211256985478

Result**✗ Failed**

- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #14

2021-01-12 09:41

MOT test number

483755913764

Result**✓ Passed**

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #13** 2021-01-11 11:38**MOT test number** 826358269227**Result** ✗ Failed**Fail** Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**MOT #12** 2019-12-16 15:27**MOT test number** 431623487808**Result** ✓ Passed**MOT #11** 2019-12-16 10:29**MOT test number** 584762550093**Result** ✗ Failed**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #10** 2019-01-09 16:21**MOT test number** 915433010202**Result** ✓ Passed

**MOT #9** 2019-01-08 12:47**MOT test number** 948549897346**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**Fail** Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**MOT #8** 2018-01-08 15:53**MOT test number** 676258917168**Result** ✓ Passed**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2018-01-08 10:11**MOT test number** 229677091108**Result** ✗ Failed**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front Suspension arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2017-01-04 13:18**MOT test number** 894566325112**Result** ✓ Passed**MOT #5** 2015-12-15 15:56**MOT test number** 436252827670**Result** ✓ Passed

**MOT #4** 2014-12-16 15:21**MOT test number** 387020554329**Result** ✓ Passed**Notice** O/s/r tyre scrubbing inner edge**Notice** N/s/f tyre scrubbing edges**MOT #3** 2013-12-18 09:49**MOT test number** 455382653348**Result** ✓ Passed**MOT #2** 2013-12-17 14:38**MOT test number** 898991753313**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Notice** Nail in offside rear tyre**MOT #1** 2012-12-21 14:42**MOT test number** 929706152382**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

X

Untaxed

Tax expired:
1 March 2024

X

MOT

Expired:
6 December 2023

Tax status	Expired at 1 March 2024
Days left	59 days too late
MOT expiry date	6 December 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-12-22
Last registration	2022-11-07
Complete history	See info



Registration #1	2009-12-22	8 mi
Registration #2	2012-12-21	61.568 mi
Registration #3	2013-12-17	73.055 mi
Registration #4	2013-12-18	73.055 mi
Registration #5	2014-12-16	85.598 mi
Registration #6	2015-12-15	92.960 mi
Registration #7	2017-01-04	106.940 mi
Registration #8	2018-01-08	122.131 mi
Registration #9	2018-01-08	122.131 mi
Registration #10	2019-01-08	133.413 mi
Registration #11	2019-01-08	133.413 mi
Registration #12	2019-01-08	133.413 mi
Registration #13	2019-01-08	133.413 mi
Registration #14	2019-01-08	133.413 mi
Registration #15	2019-01-08	133.413 mi
Registration #16	2019-01-08	133.413 mi
Registration #17	2019-01-08	133.413 mi
Registration #18	2019-01-08	133.413 mi
Registration #19	2019-01-08	133.413 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1408 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number

884000