



ML58GZP

report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT 260 LR P/V
Colour	Silver
Year of manufacture	2009
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



## MOT history

MOT expiry date	2020-11-07
MOT pass rate	53 %
MOT passed	8
Failed MOT tests	7
Total advice items	31
Total items failed	27

MOT #15 2019-05-08 16:00

MOT test number 528902040741

Result ✓ Passed

Next expiry date 2020-11-07

**Advice** Nearside sill damaged

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #14 2018-05-05 07:31

MOT test number 356414436130

Result ✓ Passed

**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**Advice** Nearside Front body work damaged

MOT #13 2018-05-05 07:31

MOT test number 111135550433

Result ✗ Failed

**Advice** Nearside Front body work damaged

**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)

**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**MOT #12**

2018-02-06 12:11

**MOT test number**

164410750325

**Result****✗ Failed**

- Advice** Front Tyre worn close to the legal limit NS & OS 215/75R16 (4.1.E.1)
- Fail** Nearside Stop lamp not working (1.2.1b)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Fail** Offside Front Seat belt anchorage prescribed area is excessively corroded inner step (5.2.6)
- Advice** Brake disc worn, pitted or scored, but not seriously weakened OSF,NSR,OSR (3.5.1i)
- Fail** Nearside Front Anti-roll bar linkage damaged and seriously weakened (2.4.G.1)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Advice** Nearside door mirror glas damaged but does not distort the veiw to the rear
- Advice** Front Suspension arm rubber bush deteriorated but not resulting in excessive movement NS & OS (2.4.G.2)
- Fail** Offside Front Brake pipe excessively corroded engine bay below servo (3.6.B.2c)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)
- Fail** Nearside Rear brake caliper leaking (3.6.A.1)
- Advice** Nearside front outer wing/wheel arch damaged

**MOT #11**

2017-01-04 16:33

**MOT test number**

431726145696

**Result****✓ Passed**

- Advice** Centre brake light not working
- Advice** Dash warning light on

**MOT #10** 2017-01-04 08:40**MOT test number** 688719822100**Result** ✗ Failed**Advice** Centre brake light not working**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Dash warning light on**Fail** Offside Rear Leaf spring cracked (2.4.B.1a)**MOT #9** 2016-01-06 12:44**MOT test number** 680552629339**Result** ✓ Passed**MOT #8** 2016-01-05 10:50**MOT test number** 272384666802**Result** ✗ Failed**Fail** Offside Rear Stop lamp not working (1.2.1b)**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Loading door cannot be secured in the closed position SIDE DOOR INSECURE (6.4.1)**Fail** Front registration plate deteriorated (6.3.1d)**Fail** Centre Rear Upper Stop lamp not working (1.2.1b)**Fail** Nearside Front Front passenger door cannot be opened from outside the vehicle (6.2.B.1b)**Fail** Exhaust emits an excessive level of metered smoke (7.4.B.3a)

**MOT #7** 2014-12-31 14:04**MOT test number** 757995664372**Result** ✓ Passed**Notice** Centre brake light not working unknown if connected**Notice** Dash warning lamp on**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #6** 2014-12-30 09:03**MOT test number** 577934764369**Result** ✗ Failed**Fail** Offside Outer Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Notice** Centre brake light not working unknown if connected**Fail** Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Fail** Front Anti-roll bar has excessive play in a pin/bush (2.4.G.2)**Advice** Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**Notice** Dash warning lamp on**Fail** Nearside Inner Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #5** 2014-01-02 08:30**MOT test number** 258002504053**Result** ✓ Passed**Notice** Nail in offside front tyre**Notice** Brake pad warning light on



<b>MOT #4</b>	2013-01-02 16:43
<b>MOT test number</b>	959872503062
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear position lamp(s) slightly affected by the operation of another lamp (1.1.A.3f)

<b>MOT #3</b>	2013-01-02 16:43
<b>MOT test number</b>	517972303018
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Nearside Registration plate lamp not working (1.1.C.1d)
<b>Pass with rectification</b>	Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)
<b>Pass with rectification</b>	Front passenger door cannot be opened from outside the vehicle (6.2.B.1b)
<b>Advice</b>	Nearside Rear position lamp(s) slightly affected by the operation of another lamp (1.1.A.3f)

<b>MOT #2</b>	2012-01-04 16:52
<b>MOT test number</b>	836134702057
<b>Result</b>	✓ Passed
<b>Notice</b>	Nearside mirror backing missing
<b>Notice</b>	Unkown if centre brake light is connected

<b>MOT #1</b>	2012-01-04 16:52
<b>MOT test number</b>	509144102064
<b>Result</b>	✗ Failed
<b>Notice</b>	Unkown if centre brake light is connected
<b>Pass with rectification</b>	Offside Registration plate lamp not working (1.1.C.1d)
<b>Notice</b>	Nearside mirror backing missing



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>ML58GZP</b>
Plate since	2019-03-28
Current registration	<b>ML58GZP</b>
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2009-01-06
Last registration	2019-05-08
Complete history	<a href="#">See info</a>



Registration #1	2009-01-06	13 mi
Registration #2	2012-01-04	28.242 mi
Registration #3	2013-01-02	58.535 mi
Registration #4	2014-01-02	83.822 mi
Registration #5	2014-12-30	111.205 mi
Registration #6	2014-12-31	111.218 mi
Registration #7	2016-01-05	131.679 mi
Registration #8	2019-05-08	151.217 mi
Registration #9	2019-05-08	151.217 mi
Registration #10	2019-05-08	151.217 mi
Registration #11	2019-05-08	151.217 mi
Registration #12	2019-05-08	151.217 mi
Registration #13	2019-05-08	151.217 mi
Registration #14	2019-05-08	151.217 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2360 mm
Height	1989 mm
Length	4863 mm
Kerb weight	1699 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	9R16420