





report date: 2024-03-28

## General information

Make	MAZDA
Model	3 MPS
Colour	Black
Year of manufacture	2007
Top speed	155 mph
0 - 60 mph	6.1 seconds
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	256 BHP
Max. torque	380 Nm at 3.000 rpm
Engine capacity	2.261 cc
Cylinders	4
Fuel type	Petrol
Consumption city	20.9 mpg
Consumption extra urban	37.7 mpg
Consumption combined	29.1 mpg
CO2 emission	231 g/km
CO2 label	L



CarCheck.co.uk page 1/12



report date: 2024-03-28

MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2021-03-08
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	10
Total items failed	8

MOT #16	2020-03-04 11:55
MOT test number	128520383732
Result	<b>✓</b> Passed
Next expiry date	2021-03-08

MOT #15	2019-02-25 09:53
MOT test number	465691039676
Result	✓ Passed

MOT #14	2018-02-28 17:36
MOT test number	412817043105
Result	✓ Passed

MOT #13	2018-02-28 13:17
MOT test number	212756753961
Result	<b>X</b> Failed
Fail Front Tyre tread depth below requirements of 1.6mm both (4.1.E.1)	

MOT #12	2017-03-03 10:52
MOT test number	566650119180
Result	<b>✓</b> Passed

CarCheck.co.uk page 2/12



report date: 2024-03-28

**MOT #11** 2016-03-02 12:23 548895477294 **MOT** test number Result ✓ Passed **MOT #10** 2015-03-09 11:58 **MOT** test number 229688465033 Result ✓ Passed **Advice** Front Tyre worn close to the legal limit (4.1.E.1) Notice Under-trays fitted obscuring some underside components

**MOT** #9 2015-02-13 16:12 **MOT test number** 429304945037 Result × Failed Fail Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3) **Notice** Under-trays fitted obscuring some underside components **Advice** Offside Inner Front Tyre worn close to the legal limit (4.1.E.1) Fail Registration plate lamp not working (1.1.C.1d) **Advice** Nearside Inner Front Tyre worn close to the legal limit (4.1.E.1) **Notice** Engine covers fitted obscuring some components in the engine bay Fail Nearside Front position lamp(s) not working (1.1.A.3b)

CarCheck.co.uk page 3/12



report date: 2024-03-28



MOT #7	2013-02-21 12:39
MOT test number	678412653033
Result	<b>✓</b> Passed
MOT #6	2013-02-21 11:15
MOT test number	966022553095
Result	<b>×</b> Failed
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

MOT #5	2012-02-27 09:14
MOT test number	146718552023
Result	✓ Passed
MOT #4	2012-02-27 09:14
MOT test number	456998352047
Result	<b>★</b> Failed
Pass with rectification	Nearside Headlamp aim too low (1.8)
Pass with rectification	Exhaust emissions Lambda reading after 2nd fast idle outside specified limits
(7.3.D.3)	

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #3	2011-04-06 09:44
MOT test number	175126491493
Result	✓ Passed
MOT #2	2010-04-19 09:16
MOT test number	551499800179
Result	✓ Passed
MOT #1	2010-04-19 07:54
MOT test number	691149300135
Result	<b>×</b> Failed
Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

CarCheck.co.uk page 5/12



KD07ZCO report date: 2024-03-28

## Tax & MOT check



MOT
Expired:
8 March 2021

Tax expired: 31 October 2020

Tax statusExpired at 31 October 2020Days left1277 days too lateMOT expiry date8 March 2021

Full MOT history See MOT history

## Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-

CarCheck.co.uk page 6/12



KD07ZC0 report date: 2024-03-28

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



KD07ZC0 report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



KD07ZCO report date: 2024-03-28

Owner history

e union mestery	
For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	
********	
************	
	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



KD07ZC0 report date: 2024-03-28

## Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

# Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-04-27
Last registration	2020-03-04
Complete history	See info



Registration #1	2007-04-27	8 mi
Registration #2	2010-04-19	27.449 mi
Registration #3	2010-04-19	27.449 mi
Registration #4	2011-04-06	37.273 mi
Registration #5	2012-02-27	45.371 mi
Registration #6	2013-02-21	52.303 mi
Registration #7	2013-02-21	52.306 mi
Registration #8	2014-02-12	60.244 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		D.777 es
Registration #15		11.777 es

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 11/12



KD07ZC0 report date: 2024-03-28

Safety ratings

NCAP rating	***
-------------	-----

**Video** <u>see crash video</u>



# Dimensions & weight

Width	1755 mm
Height	1465 mm
Length	4420 mm
Wheel base	2640 mm
Kerb weight	1483 kg
Max. allowed weight	1910 kg

# Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	L3 903872

CarCheck.co.uk page 12/12