



report date: 2024-03-29

General information

Make	VOLVO
Model	C70 D5 SPORT
Colour	Black
Year of manufacture	2007
Top speed	140 mph
0 - 60 mph	8.8 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	178 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	28.0 mpg
Consumption extra urban	49.6 mpg
Consumption combined	38.7 mpg
CO2 emission	193 g/km
CO2 label	J






Internet history

Entry 2

Date	2021-11-08
Pictures	15
Listing price	View report



source: yesauto.com

Entry 1

Date	2021-11-04
Pictures	16
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-27
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	23
Total items failed	7

MOT #16 2023-09-25 16:05

MOT test number 677468023735

Result ✓ Passed

Next expiry date 2024-09-27

- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #15 2022-09-22 10:29

MOT test number 229955471608

Result ✓ Passed

- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Slight corrosion on the front and rear subframes
- Minor** Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #14** 2021-09-28 15:30**MOT test number** 804678501522**Result** ✓ Passed**Advice** Nearside Rear Seat belt buckle slightly damaged (7.1.2 (d))**Minor** Offside Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #13** 2021-09-20 15:04**MOT test number** 658109383061**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Seat belt buckle slightly damaged (7.1.2 (d))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Minor** Offside Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Driver's door does not latch securely closed (6.2.3 (a))**MOT #12** 2020-09-02 15:50**MOT test number** 112648390747**Result** ✓ Passed**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #11** 2019-09-12 12:58**MOT test number** 887625839804**Result** ✓ Passed

**MOT #10** 2018-12-08 15:52**MOT test number** 689303117301**Result** ✓ Passed**Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Rear Bump stop missing**MOT #9** 2017-01-25 16:52**MOT test number** 328605642303**Result** ✓ Passed**Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #8** 2017-01-18 11:04**MOT test number** 774408602419**Result** ✗ Failed**Fail** Offside Inner Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #7** 2016-01-08 11:18**MOT test number** 399237067598**Result** ✓ Passed**MOT #6** 2014-09-26 10:16**MOT test number** 247429064299**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)

**MOT #5** 2014-09-26 10:16**MOT test number** 188899364208**Result** ✗ Failed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Pass with rectification** Rear Registration plate lamp not working (1.1.C.1d)**MOT #4** 2013-09-27 10:46**MOT test number** 185970173247**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-08-30 13:37**MOT test number** 738393642278**Result** ✓ Passed**MOT #2** 2011-08-30 10:16**MOT test number** 328642441497**Result** ✓ Passed**MOT #1** 2010-09-27 14:50**MOT test number** 770600570273**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
20 March 2024

✓

MOT

Expires:
27 September 2024

Tax status	Expired at 20 March 2024
Days left	39 days too late
MOT expiry date	27 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-29
Current registration	 
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-09-21
Last registration	2023-09-25
Complete history	See info



Registration #1	2007-09-21	25 mi
Registration #2	2010-09-27	21.640 mi
Registration #3	2011-08-30	40.281 mi
Registration #4	2012-08-30	65.496 mi
Registration #5	2013-09-27	73.540 mi
Registration #6	2014-09-26	83.240 mi
Registration #7	2016-01-08	92.347 mi
Registration #8	2017-01-18	105.545 mi
Registration #9	2017-01-25	105.545 mi
Registration #10	2019-05-20	105.545 mi
Registration #11	2019-05-20	105.545 mi
Registration #12	2019-05-20	105.545 mi
Registration #13	2019-05-20	105.545 mi
Registration #14	2019-05-20	105.545 mi
Registration #15	2019-05-20	105.545 mi
Registration #16	2019-05-20	105.545 mi
Registration #17	2019-05-20	105.545 mi
Registration #18	2019-05-20	105.545 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1400 mm
Length	4582 mm
Wheel base	2640 mm
Kerb weight	1684 kg
Max. allowed weight	2150 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Engine number

420029