





report date: 2024-03-28

General information

Make	NISSAN
Model	PIXO N-TEC
Colour	Black
Year of manufacture	2010
Top speed	96 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	103 g/km
CO2 label	В



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-09-22

Pictures 17

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2024-11-28
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	12
Total items failed	10

MOT #12	2023-11-21 12:51
MOT test number	190392184647
Result	✓ Passed
Next expiry date	2024-11-28
Advice Front hub caps missing	

MOT #11 2023-11-21 08:45

MOT test number 964209591665

Result X Failed

Fail Driver's view of the road through the swept area of the windscreen significantly affected by an obstruction on screen (3.1 (a) (ii))

Fail Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Fail Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt play in ball joint (5.3.4 (b) (ii))

Advice Front hub caps missing

 MOT #10
 2022-11-21 09:44

 MOT test number
 736171437849

 Result
 ✓ Passed

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

CarCheck.co.uk page 3/12



Fail

RO60YPN

report date: 2024-03-28

2021-11-29 14:59 MOT #9 451444387554 **MOT** test number Result ✓ Passed **MOT #8** 2021-03-30 13:46 **MOT** test number 157259102042 ✓ Passed Result **MOT #7** 2021-03-22 12:56 117478790415 **MOT** test number Result × Failed Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Rear Oil leaking excessively from engine main? (8.4.1 (a) (i)) Fail Fail Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i)) Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #6	2019-10-01 12:25
MO1 #6	2019-10-01 12.25
MOT test number	210438378666
Result	✓ Passed
Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Rear axle corroded	
Minor Front Inner Drive shaft joint constant velocity boot severely deteriorated Nearsid (g) (i))	e & Offside (6.1.7
Advice Front Tyre worn close to legal limit/worn on edge Nearside & Offside (5.2.3 (e))	
Advice Front Lower Suspension arm pin or bush worn but not resulting in excessive mo & Offside (5.3.4 (a) (i))	vement Nearside
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5

MOT test number

Result

Advice Front Tyre worn close to legal limit/worn on edge Nearside & Offside (5.2.3 (e))

 MOT #4
 2017-08-02 08:13

 MOT test number
 461442411908

 Result
 ✓ Passed

 MOT #3
 2016-08-03 09:42

 MOT test number
 595267475486

 Result
 ✓ Passed

 Advice
 Front Brake pad(s) wearing thin (3.5.1g)

MOT #2	2014-11-26 14:38
MOT test number	408630434338
Result	✓ Passed
MOT #1	2013-11-21 12:31
MOT test number	629365723368
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check





Expires: 28 November 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	28 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

_	
Owner	hictory
OWITE	HIISLOLY

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.		N

	More info	>
Plate changes See in this check if this NISSAN had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		0.00.00
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-11-30
Last registration	2023-11-21
Complete history	See info



Registration #1	2010-11-30	28 mi
Registration #2	2013-11-21	11.205 mi
Registration #3	2014-11-26	17.867 mi
Registration #4	2016-08-03	31.494 mi
Registration #5	2017-08-02	37.835 mi
Registration #6	2018-09-21	44.892 mi
Registration #7	2019-10-01	50.992 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
_		
Registration #13		11.777 esi

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3565 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	112085

CarCheck.co.uk page 12/12