




report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	CC GT TDI BLUEMOTION TECHNOLOGY
Colour	Blue
Year of manufacture	2012
Top speed	133 mph
0 - 100 km/h	9.8 seconds
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	103 kW / 140 HP / 138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	60.1 mpg
CO2 emission	120 g/km
CO2 label	C





Internet history

Entry 2

Date	2021-06-23
Pictures	1
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-06-23
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-12
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	18
Total items failed	2

MOT #12	2024-02-02 09:04
MOT test number	858701861024
Result	✓ Passed
Next expiry date	2025-02-12

MOT #11	2023-01-27 10:12
MOT test number	521337328956
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Electronic parking brake defective but can be satisfactorily operated (1.1.6 (d))

MOT #10	2022-02-12 13:46
MOT test number	471006404840
Result	✓ Passed

MOT #9	2021-02-08 11:02
MOT test number	318226978787
Result	✓ Passed

**MOT #8** 2020-02-06 09:50**MOT test number** 129160752049**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge 2 mm (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2 mm (5.2.3 (e))**MOT #7** 2020-02-06 09:50**MOT test number** 545169283755**Result** ✗ Failed**Pass with rectification** Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 2 mm (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2 mm (5.2.3 (e))**MOT #6** 2019-02-11 12:32**MOT test number** 104916401242**Result** ✓ Passed**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**MOT #5** 2018-02-09 11:44**MOT test number** 794579775091**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2017-02-13 10:53**MOT test number** 229443131883**Result** ✓ Passed**Advice** Unable to detect reading on emissions test

**MOT #3** 2016-11-07 09:51**MOT test number** 808765901457**Result** ✓ Passed**Advice** Under Trays & Engine Cover Fitted Obscuring Some Components**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #2** 2016-11-01 10:15**MOT test number** 575223262484**Result** ✗ Failed**Fail** Nearside Front brake caliper securing device missing Spring clip (3.5.1j)**Advice** Offside rear tyre slightly stepping on inner edge**Advice** Nearside rear tyre slightly stepping on inner edge**Advice** Covers fitted obscuring some components**MOT #1** 2015-11-03 10:04**MOT test number** 358893314905**Result** ✓ Passed**Advice** Nearside Rear tyre has a cut to outer side**Advice** Rear both tyres stepping on inner edge



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
12 February 2025

Tax status	Valid until 1 June
Days left	34
MOT expiry date	12 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 VK62OPT
Plate since	2019-06-29
Current registration	 VK62OPT
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-11-30
Last registration	2024-02-02
Complete history	See info



Registration #1	2012-11-30	14 mi
Registration #2	2015-11-03	32.347 mi
Registration #3	2016-11-01	41.037 mi
Registration #4	2016-11-07	41.047 mi
Registration #5	2017-02-13	41.848 mi
Registration #6	2018-02-09	74.604 mi
Registration #7	2019-02-11	100.974 mi
Registration #8	2020-02-06	133.497 mi
Registration #9	2020-05-20	151.277 mi
Registration #10	2020-05-20	151.277 mi
Registration #11	2020-05-20	151.277 mi
Registration #12	2020-05-20	151.277 mi
Registration #13	2020-05-20	151.277 mi
Registration #14	2020-05-20	151.277 mi
Registration #15	2020-05-20	151.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	77%
Pedestrian	54%
Safety systems	71%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	2090 mm
Height	1421 mm
Length	4902 mm
Wheel base	2710 mm
Kerb weight	1550 kg
Max. allowed weight	2050 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	CFFBD24555