





report date: 2024-03-29

General information

Make	HYUNDAI
Model	I10 SE
Colour	Silver
Year of manufacture	2017
Top speed	96 mph
0 - 60 mph	14.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	65 BHP
Max. torque	95 Nm at 3.500 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	108 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history


Entry 2

Date 2024-01-08

Pictures 36

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-06-08

Pictures 19

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/11



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-01-16
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	6
Total items failed	2

MOT #8	2024-01-17 13:55
MOT test number	571999110709
Result	✓ Passed
Next expiry date	2025-01-16

MOT #7		2023-06-06 08:42
MOT test	number	718854842643
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Items removed from driver's view prior to test	

MOT #6	2022-06-08 13:43
MOT test number	906723088621
Result	✓ Passed
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14	(a) (ii))

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #5 2022-06-08 10:49

MOT test number 268705677163

Result X Failed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Front Inner Steering rack gaiter missing or no longer prevents the ingress of dirt Clip on gaiter come off needs clip to resecure (2.1.3 (g) (ii))

MOT #4 2021-06-24 14:20

MOT test number 436376325081

Result \(\sqrt{Passed} \)

MOT #3 2021-04-12 11:31

MOT test number 517455451991

MOT #2 2020-09-08 10:58

MOT test number 763313287255

Result ✓ Passed

MOT #1 2020-09-07 13:26

MOT test number 416387708738

Result X Failed

Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	16 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

\cap	M	or	hi	ct	on
Ov	NΠ	er	ш	SU	

For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		J

	More info >	
Plate changes		
See in this check if this HYUNDAI had different number plates.		
Number of plates		
Current registration	OK SIE	
Plate since		
Current registration	UK UK	
Plate since		
	More info >	

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2017-09-25
Last registration	2024-01-17
Complete history	See info



Registration #1	2017-09-25	17 mi
Registration #2	2020-09-07	34.718 mi
Registration #3	2020-09-08	34.730 mi
Registration #4	2021-04-12	35.779 mi
Registration #5		11.777 es
Registration #6	2021-06-24	35.988 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		10.377 mg

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	79%
Children	80%
Pedestrian	71%
Safety systems	56%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1660 mm
Height	1500 mm
Length	3665 mm
Wheel base	2385 mm
Kerb weight	933 kg
Max. allowed weight	1420 kg

Additional information

Fuel tank capacity	40
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles 2

Engine number G3LAHM275871