





## General information

Make	FIAT
Model	PUNTO JTD SPORTING
Colour	Red
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	130 BHP
Max. torque	280 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	48.7 mpg





# Internet history

Entry 1

Date


2021-06-13

Pictures

Listing price

View report

6



source: autotrader.co.uk



## MOT history

MOT #14	2022-03-16 13:39
MOT test number	739426050459
Result	✓ Passed
Next expiry date	2023-03-23
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e	e))
Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice Nearside Rear hand bake low readings	
Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #13	2021-03-02 14:12
MOT test number	174764117790
Result	✓ Passed
Minor Offside Front Obligatory mirror slightly loose (3.3 (b) (i))	
Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i))	
Advice Nearside Front Coil spring modified but not seriously weakened (5.3.1 (d) (i))	

MOT #12	2020-03-24 16:04
MOT test number	197157104827
Result	✓ Passed

MOT #11	2019-04-02 12:54
MOT test number	700259035034
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #10	2018-04-26 11:58
MOT test number	210054970295
Result	✓ Passed





MOT #9	2017-02-22 10:34
MOT test number	574407517910
Result	✓ Passed
Advice Undertrays fitted	
MOT #8	2016-04-07 13:00
MOT test number	235664383334
Result	✓ Passed
MOT #7	2015-09-07 10:15
MOT test number	105952931397
Result	✓ Passed
МОТ #6	2013-12-19 17:26
MOT test number	846343453394
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #5	2013-12-19 15:05
MOT test number	906013053320
Result	× Failed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
<b>Fail</b> Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	





MOT #4	2012-12-21 14:29
MOT test number	405786752422
Result	✓ Passed
MOT #3	2011-12-22 11:54
MOT test number	426776051361
Result	✓ Passed

MOT #2	2010-12-01 14:02
MOT test number	764955330376
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #1		2010-11-25 16:15
MOT test	number	582949920392
Result		🗙 Failed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tie bar/rod has slight play in a ball joint (2.4.G.2)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Fail Of	fside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	





#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Dumage 2	E E E E
Date	J.
Category	amer
Туре	

#### Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second sec	
************	
********	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	





#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-12-20
Last registration	2022-03-16
Complete history	See info



Registration #1	2007-12-20	23 mi
Registration #2	2010-11-25	54.557 mi
Registration #3	2010-12-01	54.727 mi
Registration #4	2011-12-22	73.695 mi
Registration #5	2012-12-21	84.345 mi
Registration #6	2013-12-19	95.240 mi
Registration #7	2013-12-19	95.240 mi
Registration #8	2015-09-07	108.346 mi
Registration #9	87773-273-277	11.777 esi
-	80000-20-20 80000-20-20	11.227 est
Registration #9	8000 - 20 - 20 8000 - 20 - 20 8000 - 20 - 20	01.000 est 01.000 est 01.000 est
Registration #9 Registration #10	80000-200-20 80000-20-20 80000-20-20 80000-20-20	00.000 est 0.000 est 00.000 est 00.000 est
Registration #9 Registration #10 Registration #11	1000 - 00 - 00 1000 - 00 - 00 1000 - 00 -	01.000 est 01.000 est 01.000 est 01.000 est 01.000 est
Registration #9 Registration #10 Registration #11 Registration #12	1000 00 00 1000 00 00 1000 00 00 1000 00 00 1000 00 00 1000 00 1000 00 1000 00 1000 00 1000 00	00.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est
Registration #9 Registration #10 Registration #11 Registration #12 Registration #13	1000 00 00 1000 00 00 1000 00 00 1000 00 00 1000 00 00 1000 00 1000 00 1000 00 1000 00 1000 00	00.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est

More info >





### Car features

S0225	Air conditioning
S0295	
50482	
\$0501	
S0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

\*\*\*\* see crash video



Dimensions & weight	
Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1205 kg
Max. allowed weight	1685 kg
Additional information	
Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 11/11