



report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO 8V ACTIVE
Colour	Blue
Year of manufacture	-
Top speed	96 mph
0 - 60 mph	14.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	59 BHP
Max. torque	102 Nm at 2.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	49.6 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-04
Pictures	6
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #16	2021-11-29 09:19
MOT test number	365625431313
Result	✓ Passed
Next expiry date	2022-12-07
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #15	2020-12-08 10:44
MOT test number	978649337802
Result	✓ Passed

MOT #14	2018-10-25 14:40
MOT test number	440406847391
Result	✓ Passed

MOT #13	2018-10-22 15:23
MOT test number	625301270871
Result	✗ Failed
Fail	Front Headlamp has a product on the lens so that the light output is severely reduced both (4.1.4 (b))
Fail	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #12	2017-08-25 13:52
MOT test number	297806361033
Result	✓ Passed
Advice	Offside Vehicle structure has slight corrosion sill panel corroded (6.1.A.1)

**MOT #11** 2017-08-23 15:25**MOT test number** 515159838344**Result** ✗ Failed

- Fail** Exhaust has a major leak of exhaust gases (7.1.2)
- Fail** Front brake disc in such a condition that it is seriously weakened (3.5.1i)
- Fail** Nearside Front coil spring broken (2.4.C.1a)

MOT #10 2015-01-03 09:00**MOT test number** 355783605046**Result** ✓ Passed

- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #9 2014-02-11 09:29**MOT test number** 775892644037**Result** ✓ Passed

- Advice** Nearside Rear coil spring corroded (2.4.C.1b)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear coil spring corroded (2.4.C.1b)

MOT #8 2013-02-02 10:18**MOT test number** 307713633094**Result** ✓ Passed

- Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- Notice** Front subframe corrosion

**MOT #7** 2013-02-02 10:18**MOT test number** 208843333093**Result** ✗ Failed

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Notice Front subframe corrosion

Pass with rectification Nearside Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)

MOT #6 2012-02-11 10:03**MOT test number** 119002842056**Result** ✓ Passed

Advice Rear Upper Shock absorber has a slightly worn bush (2.7.4)

Notice Windscreen washers froze

MOT #5 2011-02-05 09:35**MOT test number** 436666031012**Result** ✓ Passed

Advice Offside Rear Upper Shock absorber has a slightly worn bush (2.7.4)

Notice Nail in offside rear tyre

Advice Nearside Rear Upper Shock absorber has a slightly worn bush (2.7.4)

MOT #4 2011-02-05 09:35**MOT test number** 188106131070**Result** ✗ Failed

Pass with rectification Windscreen wiper does not clear the windscreen effectively (8.2.2)

Notice Nail in offside rear tyre

Advice Offside Rear Upper Shock absorber has a slightly worn bush (2.7.4)

Advice Nearside Rear Upper Shock absorber has a slightly worn bush (2.7.4)



MOT #3	2010-02-06 12:51
MOT test number	470577530006
Result	✓ Passed
Advice	Nearside Rear Upper Shock absorber has a slightly worn bush (2.7.4)

MOT #2	2009-02-07 11:22
MOT test number	630058439084
Result	✓ Passed

MOT #1	2008-02-14 09:29
MOT test number	921665148073
Result	✓ Passed



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2004-11-29
Last registration	2021-11-29
Complete history	See info



Registration #1	2004-11-29	10 mi
Registration #2	2008-02-14	32.339 mi
Registration #3	2009-02-07	32.391 mi
Registration #4	2010-02-06	35.733 mi
Registration #5	2011-02-05	39.162 mi
Registration #6	2012-02-11	42.430 mi
Registration #7	2013-02-02	45.421 mi
Registration #8	2014-02-11	51.236 mi
Registration #9	2015-02-02	55.277 mi
Registration #10	2016-02-02	55.277 mi
Registration #11	2017-02-02	55.277 mi
Registration #12	2018-02-02	55.277 mi
Registration #13	2019-02-02	55.277 mi
Registration #14	2020-02-02	55.277 mi
Registration #15	2021-02-02	55.277 mi
Registration #16	2022-02-02	55.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1480 mm
Length	3865 mm
Wheel base	2460 mm
Kerb weight	875 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	2095410