





report date: 2024-03-29

General information

Make	FORD
Model	KUGA LX TDCI
Colour	Black
Year of manufacture	-
Top speed	122 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.1 mpg



CarCheck.co.uk page 1/11



report date: 2024-03-29


Internet history

Entry 1

Date 2021-05-21

Pictures 64

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

2017-12-12 10:33

MOT history

MOT #9

MOI #13	2021-05-27 09:00
MOT test number	985763677543
Result	✓ Passed
Next expiry date	2022-05-26
MOT #12	2020-11-19 12:58
MOT test number	825354561678
Result	✓ Passed

MOT #11	2019-10-31 14:45
MOT test number	136855723741
Result	✓ Passed

MOT #10	2018-11-20 12:58
MOT test number	321969712941
Result	✓ Passed
Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	

MOT test number	790879612634
Result	✓ Passed
MOT #8	2016-11-21 11:18
MOT test number	171902885854
Result	✓ Passed
Advice Child Seat fitted not allowing full inspection of adult belt	
Advice Both rear tyres perished	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #7		2015-12-01 11:59
MOT test	number	442402266486
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #6	2015-12-01 11:59	
MOT test number	904477824184	
Result	X Failed	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)		
Pass with rectification Headlamp cleaning device inoperative (1.7.2)		
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)		
Pass with rectification Windscreen washer provides insufficient washer liquid (8.2.3)		

MOT #5	2014-12-01 10:38
MOT test number	809805734354
Result	✓ Passed
MOT #4	2013-12-06 13:12
MOT test number	418110243464
Result	✓ Passed
MOT #3	2012-12-10 13:15
MOT test number	738665842399
Result	✓ Passed
MOT #2	2011-12-21 10:12
MOT test number	639335651304
Result	✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29

MOT #1		2011-10-18 10:04
MOT test	number	127521491215
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



OV58GKL report date: 2024-03-29

Owner history

e mier metery	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	UK NEW
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2008-10-24
Last registration	2021-05-27
Complete history	See info



Registration #1	2008-10-24	20 mi
Registration #2	2011-10-18	26.079 mi
Registration #3	2011-12-21	26.850 mi
Registration #4	2012-12-10	35.531 mi
Registration #5	2013-12-06	45.042 mi
Registration #6	2014-12-01	56.971 mi
Registration #7	2015-12-01	70.345 mi
Registration #8	2015-12-01	70.345 mi
Registration #9		9.70 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		11.117 es

More info >

CarCheck.co.uk page 10/11



OV58GKL report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1736 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 11/11

Number of axles2Engine number8R41969