





report date: 2024-03-28

General information

Make	MERCEDES
Model	C C200 KOMPRESSOR SPORT
Colour	Black
Year of manufacture	2008
Top speed	140 mph
Gearbox	5 speed automatic

Engine & fuel consumption

Power	181 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.796 сс
Cylinders	4
Fuel type	Petrol
Consumption city	25.2 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.9 mpg
CO2 emission	198 g/km
CO2 label	1



CarCheck.co.uk page 1/16



report date: 2024-03-28

Internet history

Entry 1

Date 2022-01-18

Pictures 35

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/16



PF08KUR report date: 2024-03-28

MOT history

MOT expiry date	2025-02-28
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	41
Total items failed	13

MOT #20		2024-02-29 17:19
MOT test	number	936739559325
Result		✓ Passed
Next expi	ry date	2025-02-28
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1	.11 (c))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing scrubbing edge	e (5.2.3 (d) (ii))
Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))		
Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))		
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1	1.11 (c))

CarCheck.co.uk page 3/16



Fail

PF08KUR

report date: 2024-03-28

MOT #19 2024-02-26 09:32 569455699170 **MOT** test number Result × Failed **Advice** Nearside Front Tyre slightly damaged/cracking or perishing scrubbing edge (5.2.3 (d) (ii)) **Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) **Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Offside Front Lower Suspension arm ball joint excessively worn camber (5.3.4 (a) (i)) Fail Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii)) Fail Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) **Advice**

MOT #18		2023-01-31 11:44
MOT test	number	400983805812
Result		✓ Passed
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Advice Nearside Front Outer Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)))

Nearside Front Lower Suspension arm ball joint excessively worn camber (5.3.4 (a) (i))

MOT #17	2022-02-22 11:29
MOT test number	605375775430
Result	✓ Passed

CarCheck.co.uk page 4/16



report date: 2024-03-28

MOT #16 2021-11-16 16:50
MOT test number 803082645943

Result ✓ Passed

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #15 2020-11-17 09:31

MOT test number 900477949706

Result ✓ Passed

MOT #14 2019-11-13 15:36

MOT test number 594917087457

Result
✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13 2018-11-15 13:31

MOT test number 725230250886

Result

Passed

MOT #12 2017-11-15 10:07

MOT test number 727671954057

CarCheck.co.uk page 5/16



report date: 2024-03-28

MOT test number

269078473459

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Front Inner Brake pad(s) wearing thin (3.5.1g)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #10 2016-11-09 09:21 **MOT** test number 639481145328 Result **X** Failed Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1) Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Pass with rectification Rear registration plate character(s) incorrectly spaced (6.3.4a) **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Advice Front Inner Brake pad(s) wearing thin (3.5.1g) Pass with rectification Front registration plate character(s) incorrectly spaced (6.3.4a)

MOT #9	2015-11-16 11:24
MOT test number	170769184760
Result	✓ Passed

CarCheck.co.uk page 6/16



report date: 2024-03-28

MOT test number

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #7 2014-11-21 10:29 **MOT** test number 217715024399 Result × Failed **Pass with rectification** Rear registration plate character(s) incorrectly spaced (6.3.4a) **Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1) **Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1) Pass with rectification Front registration plate character(s) incorrectly spaced (6.3.4a) **Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1) **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #6

MOT test number

Result

Notice Rear tyres worn low .Offside on wear bars.

Pass with rectification

Offside Headlamp not working on dipped beam (1.7.5a)

CarCheck.co.uk page 7/16



report date: 2024-03-28

MOT #5 2013-06-28 16:20 MOT test number 539539273130

Notice Rear tyres worn low .Offside on wear bars.

MOT #4 2012-07-06 16:28

MOT test number 419268682134

Result \(\sqrt{Passed} \)

MOT #3 2012-07-06 11:16

MOT test number 516558682123

Result X Failed

Fail Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail Front brake disc in such a condition that it is seriously weakened (3.5.1i)

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #2 2011-08-10 16:54

MOT test number 988442721265

Advice Nearside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Notice Spare wheel missing.

Notice Rear reg plate loose.

CarCheck.co.uk page 8/16



report date: 2024-03-28

MOT test number
675482321217

Result

Pass with rectification
Offside Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)

Notice
Spare wheel missing.

Advice
Nearside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Notice
Rear reg plate loose.

CarCheck.co.uk page 9/16



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 June
Days left	34
MOT expiry date	28 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 10/16



report date: 2024-03-28

Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date

Category
Type

Damage 2

Category

Date

Туре



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/16



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 12/16



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downlo <u>here</u> .	

	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	IK SIE
Plate since	
Current registration	NE UK
Plate since	
	Moro info

CarCheck.co.uk page 13/16



report date: 2024-03-28

Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

Contact info

More info >

CarCheck.co.uk page 14/16



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-06-26
Last registration	2024-02-29
Complete history	See info



Registration #1	2008-06-26	25 mi
Registration #2	2011-08-10	27.466 mi
Registration #3	2012-07-06	42.582 mi
Registration #4	2012-07-06	42.582 mi
Registration #5	2013-06-28	58.588 mi
Registration #6	2014-11-21	69.467 mi
Registration #7	2015-11-16	76.478 mi
Registration #8	2016-11-09	82.064 mi
Registration #9	2016-11-09	82.064 mi
Registration #10	2017-11-15	85.822 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		0.77 44
Registration #19		11.777 es

More info >

CarCheck.co.uk page 15/16



report date: 2024-03-28

Dimensions & weight

Width	1770 mm
Height	1459 mm
Length	4596 mm
Wheel base	2760 mm
Kerb weight	1555 kg

Additional information

Fuel tank capacity	62 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	27195031101770

CarCheck.co.uk page 16/16