



BUI3FHX

report date: 2024-03-29

General information

Make	SUZUKI
Model	ALTO SZ
Colour	White
Year of manufacture	2013
Top speed	96 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A





MOT history

MOT expiry date	2024-06-30
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	23
Total items failed	5

MOT #11	2023-06-22 12:44
MOT test number	596774566351
Result	✓ Passed
Next expiry date	2024-06-30
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10	2023-06-22 09:35
MOT test number	849102870162
Result	✗ Failed
Fail	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Fail	Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #9** 2022-06-15 10:46**MOT test number** 667457057948**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #8** 2021-07-01 10:44**MOT test number** 780820546219**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin both side (1.1.13 (a) (ii))**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**MOT #7** 2020-06-26 10:15**MOT test number** 536593245440**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin both (1.1.13 (a) (ii))**MOT #6** 2019-05-11 10:30**MOT test number** 562212648576**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2019-05-11 10:30**MOT test number** 861053381375**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #4** 2018-05-12 09:39**MOT test number** 232915631769**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Wear on nearside rear tyre**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2017-05-22 15:54**MOT test number** 240281205325**Result** ✓ Passed**MOT #2** 2016-08-24 15:45**MOT test number** 749670061378**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #1** 2016-08-24 15:45**MOT test number** 321015187370**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
30 June 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	30 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	BU13FHX
Plate since	2019-03-29
Current registration	BU13FHX
Plate since	2019-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-05-11
Last registration	2023-06-22
Complete history	See info



Registration #1	2013-05-11	20 mi
Registration #2	2016-08-24	31.621 mi
Registration #3	2016-08-24	31.621 mi
Registration #4	2017-05-22	32.095 mi
Registration #5	2018-05-12	34.533 mi
Registration #6	2019-05-11	37.130 mi
Registration #7	2020-05-22	39.277 mi
Registration #8	2021-05-22	41.277 mi
Registration #9	2022-05-22	43.277 mi
Registration #10	2023-05-22	45.277 mi
Registration #11	2023-05-22	45.277 mi
Registration #12	2023-05-22	45.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	55%
Children	46%
Pedestrian	35%
Safety systems	29%
Overall rating	47%
Video	see crash video



Dimensions & weight

Width	1600 mm
Height	1470 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	930 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	K10BN 1640153