



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	SCENIC DYNAMIQUE TOMTOM BOSE PACK DCI
Colour	Black
Year of manufacture	2011
Top speed	112 mph
0 - 100 km/h	12.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	78 kW / 106 HP / 110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.7 mpg
CO2 emission	128 g/km
CO2 label	D






Internet history

Entry 1

Date	2021-11-10
Pictures	9
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-03-22
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	9
Total items failed	14

MOT #14	2023-03-09 17:21
MOT test number	107820300519
Result	✓ Passed
Next expiry date	2024-03-22

MOT #13	2022-03-21 12:52
MOT test number	384402907252
Result	✓ Passed
Advice	Offside Front Outer Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12	2021-02-26 09:29
MOT test number	521043175402
Result	✓ Passed
Minor	Offside Front Headlamp lens slightly defective deteriorated (4.1.1 (b) (i))

**MOT #11**

2021-02-24 11:09

**MOT test number**

736412534656

**Result****✗ Failed**

- Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Minor** Offside Front Headlamp lens slightly defective deteriorated (4.1.1 (b) (i))
- Fail** Nearside Side repeater incorrect colour (4.4.3 (a))

**MOT #10**

2020-03-04 08:46

**MOT test number**

939687283944

**Result****✓ Passed**

- Advice** Offside Front Outer Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #9**

2019-03-06 11:47

**MOT test number**

282863024289

**Result****✓ Passed**

- Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #8** 2019-03-06 10:22**MOT test number** 216285016494**Result** ✗ Failed**Fail** Nearside Front Position lamp not working (4.2.1 (a))**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Fail** Offside Front Position lamp not working (4.2.1 (a))**MOT #7** 2018-03-21 12:03**MOT test number** 234010377414**Result** ✓ Passed**MOT #6** 2018-03-21 12:03**MOT test number** 195244886216**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Front position lamp(s) not working Sidelight (1.1.A.3b)**MOT #5** 2017-03-23 10:30**MOT test number** 642638864227**Result** ✓ Passed**MOT #4** 2016-02-17 12:03**MOT test number** 530701491169**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



MOT #3	2015-02-17 09:44
MOT test number	925598745097
Result	✓ Passed
MOT #2	2014-03-07 15:05
MOT test number	875316364089
Result	✓ Passed
MOT #1	2014-03-07 15:05
MOT test number	748896964016
Result	✗ Failed
Pass with rectification	Offside Headlamp not working on dipped beam (1.7.5a)



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.


Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-03-04
Last registration	2023-03-09
Complete history	<a href="#">See info</a>



Registration #1	2011-03-04	11 mi
Registration #2	2014-03-07	45.441 mi
Registration #3	2015-02-17	56.625 mi
Registration #4	2016-02-17	66.552 mi
Registration #5	2017-03-23	75.818 mi
Registration #6	2018-03-21	85.565 mi
Registration #7	2018-03-21	85.565 mi
Registration #8	2019-03-06	97.468 mi
Registration #9	2020-03-09	100,000 mi
Registration #10	2021-03-09	100,000 mi
Registration #11	2022-03-09	100,000 mi
Registration #12	2023-03-09	100,000 mi
Registration #13	2024-03-09	100,000 mi
Registration #14	2025-03-09	100,000 mi
Registration #15	2026-03-09	100,000 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1486 mm
Height	1637 mm
Length	4344 mm
Wheel base	2703 mm
Kerb weight	1385 kg
Max. allowed weight	1944 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D246598