



report date: 2024-03-28

General information

Make	VOLVO
Model	S80 D5 SE LUX
Colour	Black
Year of manufacture	2006
Top speed	140 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	182 BHP
Max. torque	400 Nm at 2.750 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	27.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	38.7 mpg
CO2 emission	193 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-08-13
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-15
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	26
Total items failed	16

MOT #18 2024-03-16 16:48

MOT test number 550946179578

Result ✓ Passed

Next expiry date 2025-03-15

Advice Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #17 2024-03-16 16:48

MOT test number 277475455419

Result ✗ Failed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

MOT #16 2020-08-17 11:38

MOT test number 275625326466

Result ✓ Passed

Advice Brake pad(s) wearing thin Both front (1.1.13 (a) (ii))

Advice Undertrays fitted

Advice Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

**MOT #15**

2020-08-14 18:03

MOT test number

518584993695

Result

✗ Failed

- Advice** Brake pad(s) wearing thin Both front (1.1.13 (a) (ii))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Undertrays fitted
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Nearside Rear Body not fully secure (6.2.2 (a) (i))
- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #14

2019-08-14 14:58

MOT test number

380403141916

Result

✓ Passed

- Minor** Windscreen wiper blade defective 2x front (3.4 (b) (i))
- Advice** Nearside Front Play in steering rack inner joint(s)

MOT #13

2018-08-14 14:14

MOT test number

341891682055

Result

✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front tyre worn edges

**MOT #12** 2018-07-13 11:53**MOT test number** 483677561249**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge wear (5.2.3 (e))**Fail** Rear Registration plate inscription illegible (0.1 (b))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge wear (5.2.3 (e))**Fail** Nearside Body panel damaged and likely to cause injury door mirror cover missing (6.2.1 (a) (i))**MOT #11** 2017-06-23 12:07**MOT test number** 680669658046**Result** ✓ Passed**Advice** Offside Front Seat belt stitching slightly frayed (5.2.2b)**MOT #10** 2017-06-22 14:34**MOT test number** 462805515925**Result** ✗ Failed**Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Offside Front Seat belt stitching slightly frayed (5.2.2b)**Fail** Offside Stop lamp not working (1.2.1b)**MOT #9** 2015-09-03 00:00**MOT test number** 869840701270**Result** ✓ Passed

**MOT #8** 2014-08-18 14:14**MOT test number** 648950534228**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2013-08-29 09:19**MOT test number** 885541343229**Result** ✓ Passed**MOT #6** 2012-08-23 11:54**MOT test number** 345126932234**Result** ✓ Passed**MOT #5** 2012-08-23 10:25**MOT test number** 416586732264**Result** ✗ Failed**Fail** Offside Headlamp aim too high (1.8)**Fail** Nearside Headlamp aim too high (1.8)**Fail** Offside Steering rack gaiter insecure (2.2.D.2d)**MOT #4** 2011-09-01 09:22**MOT test number** 256194341230**Result** ✓ Passed**Notice** Slight movement evident in o/s inner steering rack joint

**MOT #3** 2011-09-01 09:22**MOT test number** 349994141404**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Notice** Slight movement evident in o/s inner steering rack joint**MOT #2** 2010-09-03 16:12**MOT test number** 181386740237**Result** ✓ Passed**MOT #1** 2009-09-02 14:06**MOT test number** 432485949217**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt



Tax & MOT check

X

Untaxed

Tax expired:
8 June 2021

✓

MOT

Expires:
15 March 2025

Tax status	Expired at 8 June 2021
Days left	1055 days too late
MOT expiry date	15 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 OY56RXA
Plate since	2019-09-29
Current registration	 OY56RXA
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-09-04
Last registration	2024-03-16
Complete history	See info



Registration #1	2006-09-04	14 mi
Registration #2	2009-09-02	25.129 mi
Registration #3	2010-09-03	36.277 mi
Registration #4	2011-09-01	46.947 mi
Registration #5	2012-08-23	57.337 mi
Registration #6	2012-08-23	57.337 mi
Registration #7	2013-08-29	69.519 mi
Registration #8	2014-08-18	80.155 mi
Registration #9	2015-09-03	91.142 mi
Registration #10	2017-06-22	101.527 mi
Registration #11	2019-05-20	111.912 mi
Registration #12	2019-05-20	111.912 mi
Registration #13	2019-05-20	111.912 mi
Registration #14	2019-05-20	111.912 mi
Registration #15	2019-05-20	111.912 mi
Registration #16	2019-05-20	111.912 mi
Registration #17	2019-05-20	111.912 mi
Registration #18	2019-05-20	111.912 mi
Registration #19	2019-05-20	111.912 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2106 mm
Height	1493 mm
Length	4851 mm
Wheel base	2835 mm
Kerb weight	1587 kg
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number

418526