





report date: 2024-03-29

General information

Make	VOLVO
Model	V40 T2 R-DESIGN
Colour	Black
Year of manufacture	2017
Top speed	118 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	220 Nm at 1.100 rpm
Engine capacity	1.969 сс
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	127 g/km
CO2 label	D



CarCheck.co.uk page 1/11



Internet history

Entry 7

Date 2023-10-12

Pictures 20

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 6

Date	2021-10-11
Pictures	0
Listing price	<u>View report</u>

source: heycar.co.uk

Entry 5

Date 2021-10-10

Pictures 40

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 4

Date	2021-09-06
Pictures	1
Listing price	View report

CarCheck.co.uk page 2/11



source: autoonline.co.uk

Entry 3

Date	2021-09-06
Pictures	0
Listing price	View report

source: heycar.co.uk

Entry 2

Date	2021-09-05
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Date	2021-09-05
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT h	nistory
-------	---------

Minor

MOT expiry date	2024-10-31
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	8
Total items failed	1

MOT #8	2023-11-01 12:00
MOT test number	320992544554
Result	✓ Passed
Next expiry date	2024-10-31

MOT #7		2023-10-31 15:06
MOT test nui	mber	595926633644
Result		X Failed
MAJOR O	bligatory mirror missing internal mirror has no glass (3.3 (a))	

MOT #6	2023-07-18 07:48
MOT test number	242985448866
Result	✓ Passed
MOT #5	2022-07-23 10:27
MOT test number	524590999699

Result Passed

Advice Nearside Front Inner Road wheel slightly distorted bead rim (5.2.2 (c) (i))

Windscreen damaged but not adversely affecting driver's view several small chips (3.2 (a) (i))

CarCheck.co.uk page 3/11



MOT #4 2021-08-05 12:43
MOT test number 645868238158

Advice

Nearside Rear tyre close to wear bars

MOT #3 2021-08-05 08:14 MOT test number 693251757670

Result × Failed

Advice Nearside Rear tyre close to wear bars

MAJOR Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

MAJOR Rear Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))

MAJOR Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))

MOT #2 2020-08-04 07:44

MOT test number 773851194447

Result ✓ Passed

MOT #1 2020-08-04 07:44

MOT test number 769573974214

Result X Failed

Pass with rectification Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	31 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

e when miscory	
For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	OK SIN
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2017-11-25
Last registration	2023-11-01
Complete history	See info



Registration #1	2017-11-25	16 mi
Registration #2	2020-08-04	33.247 mi
Registration #3	2020-08-04	33.247 mi
Registration #4	2021-08-05	37.874 mi
Registration #5	2021-08-05	37.876 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



Dimensions & weight

Width	2041 mm
Height	1439 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1457 kg
Max. allowed weight	1965 kg

Additional information

Fuel tank capacity	62 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/2

Number of axles2Engine number2032759