



PEUGEOT

AE63GBY


report date: 2024-03-28

General information

| | |
|---------------------|----------------------|
| Make | PEUGEOT |
| Model | PARTNER HDI S L1 850 |
| Colour | Silver |
| Year of manufacture | 2013 |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-----------------|----------|
| Power | 90 BHP |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| CO2 emission | 138 g/km |
| CO2 label | E |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-02-03 |
| Pictures | 1 |
| Listing price | View report |



source: autoonline.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-06-30 |
| MOT pass rate | 67 % |
| MOT passed | 8 |
| Failed MOT tests | 4 |
| Total advice items | 13 |
| Total items failed | 9 |

| | |
|------------------|------------------|
| MOT #12 | 2023-06-28 11:26 |
| MOT test number | 539628712722 |
| Result | ✓ Passed |
| Next expiry date | 2024-06-30 |

| | |
|---|------------------|
| MOT #11 | 2023-06-28 11:26 |
| MOT test number | 648111398003 |
| Result | ✗ Failed |
| Pass with rectification Offside Position lamp not working (4.2.1 (a) (ii)) | |

| | |
|---|------------------|
| MOT #10 | 2022-06-16 08:27 |
| MOT test number | 471125795171 |
| Result | ✓ Passed |
| Advice Front Service brake fluctuating, but not excessively Both front. (1.2.1 (e)) | |
| Advice Offside Rear Tyre slightly damaged/cracking or perishing Tyre cracking in tread pattern. (5.2.3 (d) (ii)) | |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge Tyre worn on edge and low tread. (5.2.3 (e)) | |

| | |
|-----------------|------------------|
| MOT #9 | 2021-06-26 10:37 |
| MOT test number | 239890038954 |
| Result | ✓ Passed |

**MOT #8** 2021-06-26 10:37**MOT test number** 317140160847**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #7** 2020-07-01 08:35**MOT test number** 819211713021**Result** ✓ Passed**MOT #6** 2019-08-20 10:22**MOT test number** 547072723290**Result** ✓ Passed**Advice** Vehicles internal headlight adjuster altered to recheck lights**MOT #5** 2019-08-20 10:22**MOT test number** 379779894140**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))**Pass with rectification** Upper Stop lamp(s) not working (4.3.1 (a) (ii))**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**Advice** Vehicles internal headlight adjuster altered to recheck lights**MOT #4** 2018-08-22 08:27**MOT test number** 310286922252**Result** ✓ Passed**Advice** Engine cover(s)/Undershield(s) fitted obscuring some components



| | |
|-----------------|---|
| MOT #3 | 2017-08-16 12:50 |
| MOT test number | 846673055004 |
| Result | ✓ Passed |
| Advice | Spare tyre defective |
| Advice | Clutch pedal anti-slip provision split |
| Advice | Offside Rear Tyre worn close to the legal limit (4.1.E.1) |
| Advice | Engine cover(s)/Undershield(s) fitted obscuring some components |

| | |
|-----------------|--|
| MOT #2 | 2017-08-16 10:47 |
| MOT test number | 398191613391 |
| Result | ✗ Failed |
| Fail | Offside Front Headlamp not working on dipped beam (1.7.5a) |
| Advice | Offside Rear Tyre worn close to the legal limit (4.1.E.1) |
| Advice | Clutch pedal anti-slip provision split |
| Fail | Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a) |
| Fail | Offside Registration plate lamp not working (1.1.C.1d) |
| Advice | Engine cover(s)/Undershield(s) fitted obscuring some components |

| | |
|-----------------|------------------|
| MOT #1 | 2016-08-23 14:18 |
| MOT test number | 658379042677 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
30 June 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 May |
| Days left | 1 |
| MOT expiry date | 30 June 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|----------------------------------|------------|
| Vehicle class | 39 |
| Standard rate (12 months) | £ 275,00,- |
| Standard rate (6 months) | £ 151,25,- |



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | AE63GBY |
| Plate since | 2024-03-28 |
| Current registration | AE63GBY |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 14 |
| First mileage registration | 2013-09-25 |
| Last registration | 2023-06-28 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2013-09-25 | 27 mi |
| Registration #2 | 2016-08-23 | 19.350 mi |
| Registration #3 | 2017-08-16 | 25.296 mi |
| Registration #4 | 2017-08-16 | 25.296 mi |
| Registration #5 | 2018-08-22 | 28.451 mi |
| Registration #6 | 2019-08-20 | 30.517 mi |
| Registration #7 | 2019-08-20 | 30.517 mi |
| Registration #8 | 2020-06-28 | 30.517 mi |
| Registration #9 | 2020-06-28 | 30.517 mi |
| Registration #10 | 2020-06-28 | 30.517 mi |
| Registration #11 | 2020-06-28 | 30.517 mi |
| Registration #12 | 2020-06-28 | 30.517 mi |
| Registration #13 | 2020-06-28 | 30.517 mi |
| Registration #14 | 2023-06-28 | 30.517 mi |

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 2 |
| Engine number | JBEM0211217 |