



report date: 2024-03-28

General information

| | |
|---------------------|--------------------|
| Make | BMW |
| Model | X3 XDRIVE20I XLINE |
| Colour | White |
| Year of manufacture | 2018 |
| Top speed | 134 mph |
| 0 - 60 mph | 8.3 seconds |
| Gearbox | 8 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 181 BHP |
| Max. torque | 290 Nm at 4.250 rpm |
| Engine capacity | 1.998 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 32.5 mpg |
| Consumption extra urban | 44.1 mpg |
| Consumption combined | 31.4 mpg |
| CO2 emission | 166 g/km |
| CO2 label | H |





Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2022-11-14 |
| Pictures | 0 |
| Listing price | View report |

source: [carcraft.co.uk](#)

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-12-09 |
| Pictures | 38 |
| Listing price | View report |



source: [cargurus.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-01-16 |
| MOT pass rate | 67 % |
| MOT passed | 4 |
| Failed MOT tests | 2 |
| Total advice items | 17 |
| Total items failed | 3 |

MOT #6 2024-01-04 11:26

MOT test number 582274467353

Result ✓ Passed

Next expiry date 2025-01-16

Advice Nearside Rear Tyre slightly damaged/cracking or perishing tread perished (5.2.3 (d) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge tread low (5.2.3 (e))

Advice Offside Front bellows split on front shock absorber

Advice Offside Front Tyre slightly damaged/cracking or perishing tread perished (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing tread perished (5.2.3 (d) (ii))

Advice Nearside Front bellows split on front shock absorber

MOT #5 2023-01-17 15:24

MOT test number 609732811209

Result ✓ Passed

Advice Offside Front dust cover on shock absorber split

Advice Nearside Rear Tyre slightly damaged/cracking or perishing cracking between tread (5.2.3 (d) (ii))

Advice Nearside Front dust cover on shock absorber split

Advice Offside Front Tyre slightly damaged/cracking or perishing cracking between tread (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing cracking between tread (5.2.3 (d) (ii))

**MOT #4** 2023-01-17 15:24**MOT test number** 234872116446**Result** ✗ Failed**Advice** Offside Front dust cover on shock absorber split**Advice** Offside Front Tyre slightly damaged/cracking or perishing cracking between tread (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracking between tread (5.2.3 (d) (ii))**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))**Advice** Nearside Front dust cover on shock absorber split**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracking between tread (5.2.3 (d) (ii))**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**MOT #3** 2022-03-25 10:03**MOT test number** 347407911569**Result** ✓ Passed**MOT #2** 2021-05-21 09:24**MOT test number** 921940644874**Result** ✓ Passed**MOT #1** 2021-05-19 08:14**MOT test number** 669735933098**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
16 January 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 January |
| Days left | 247 |
| MOT expiry date | 16 January 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--------------------------------------|------------|
| Vehicle class | 48 |
| Band | I |
| First licence fee (12 months) | £ 645,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this BMW had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2019-06-20 |
| Current registration | |
| Plate since | 2019-06-20 |

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 9 |
| First mileage registration | 2018-06-08 |
| Last registration | 2024-01-04 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2018-06-08 | 16 mi |
| Registration #2 | 2021-05-19 | 14.340 mi |
| Registration #3 | 2021-05-21 | 14.340 mi |
| Registration #4 | 2021-05-21 | 14.340 mi |
| Registration #5 | 2022-03-25 | 18.776 mi |
| Registration #6 | 2022-03-25 | 18.776 mi |
| Registration #7 | 2022-03-25 | 18.776 mi |
| Registration #8 | 2022-03-25 | 18.776 mi |
| Registration #9 | 2024-01-04 | 18.776 mi |

More info >



Car features

The BMW factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 88% |
| Children | 83% |
| Pedestrian | 53% |
| Safety systems | 71% |
| Overall rating | 78% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1891 mm |
| Height | 1676 mm |
| Length | 4708 mm |
| Wheel base | 2864 mm |
| Kerb weight | 1715 kg |
| Max. allowed weight | 2400 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 65 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|------------------------|----------|
| Number of axles | 2 |
| Engine number | H0383012 |