





report date: 2024-03-29

#### General information

Make	VOLKSWAGEN
Model	FOX URBAN FOX
Colour	Red
Year of manufacture	2009
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 сс
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/13



report date: 2024-03-29

## Internet history

#### Entry 1

Date 2022-02-24

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

# MOT history

MOT expiry date	2024-11-09
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	16
Total items failed	6

MOT #16	2023-10-27 16:15
MOT test number	937810728856
Result	✓ Passed
Next expiry date	2024-11-09
Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))	

MOT #15	2022-11-10 13:56
MOT test number	329105690263
Result	<b>✓</b> Passed
Advice Front Exhaust has a minor leak of exhaust gases flexible area (6.1.2 (a))	

MOT #14	2022-03-08 15:02
MOT test number	845381381627
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

**MOT #13** 2022-03-07 16:53 **MOT** test number 619597583423 Result × Failed **Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b)) Fail Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #12

MOT test number

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #11

MOT test number

Result

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT test number

Result

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Pass with rectification Front Windscreen washer provides insufficient washer liquid (3.5 (a))

CarCheck.co.uk page 4/13



report date: 2024-03-29

× Failed

MOT #9 2019-09-02 13:45

MOT test number 173045655253

Result \rightarrow Passed

Advice

Result

Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #8 2019-09-02 10:32

**MOT test number** 255991570801

Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Nearside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))

Fail Offside Headlamp not working on main beam (4.1.1 (a) (ii))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #7** 2018-08-29 11:43

MOT test number 169880306720

Result 

Passed

MOT #6 2017-08-15 12:53

MOT test number 834850465526

Result 

Passed

**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #5** 2016-09-02 11:15

**MOT test number** 964882717408

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #4 2015-08-21 08:59

**MOT test number** 898181543094

**Result** ✓ Passed

MOT #3 2014-09-08 09:25

MOT test number 956381354288

**Result** ✓ Passed

MOT #2 2013-07-06 11:34

**MOT test number** 766747883130

**Result** ✓ Passed

MOT #1 2012-07-28 09:58

**MOT test number** 689460612202

Result \( \sqrt{Passed} \)

**Notice** Both front tyres worn on inside edge.

**Advice** Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/13



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	9 November 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

#### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	

Date

Category

**Type** 



#### Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

# Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	
***************************************	
***************************************	
*******	
	More info >
Plate changes  See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	
Current registration	IK SIE
Plate since	
Current registration	NK SIK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

#### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-08-01
Last registration	2023-10-27
Complete history	See info



Registration #1	2009-08-01	16 mi
Registration #2	2012-07-28	11.275 mi
Registration #3	2013-07-06	14.761 mi
Registration #4	2014-09-08	18.001 mi
Registration #5	2015-08-21	19.295 mi
Registration #6	2016-09-02	21.946 mi
Registration #7	2017-08-15	24.757 mi
Registration #8	2018-08-29	30.869 mi
Registration #9	2019-09-02	31.860 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.177 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

#### Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	<b>★★★★</b> ★
Video	see crash video



# Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

#### Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	3
CarChack co.uk	nago 12/12

CarCheck.co.uk page 13/13

Number of seats	4
Number of axles	2
Engine number	CHF 004629