



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE LUNA 8V
Colour	Black
Year of manufacture	2007
Top speed	111 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	147 Nm at 3.800 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	180 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-06-14
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-09-26
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	13
Total items failed	4

MOT #18	2023-09-09 10:17
MOT test number	297292246573
Result	✓ Passed
Next expiry date	2024-09-26

MOT #17	2022-09-27 13:03
MOT test number	151092882752
Result	✓ Passed
<div>Advice</div> Service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.2.2 (a) (i))	

MOT #16	2021-06-14 16:55
MOT test number	856340584447
Result	✓ Passed

MOT #15	2020-07-10 12:06
MOT test number	753630584209
Result	✓ Passed

**MOT #14** 2020-07-10 09:46**MOT test number** 343972677420**Result** ✗ Failed

DANGEROUS Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #13 2019-04-30 16:43**MOT test number** 107361832335**Result** ✓ Passed**MOT #12** 2018-07-24 15:57**MOT test number** 155492498069**Result** ✓ Passed**MOT #11** 2017-07-05 09:59**MOT test number** 681824165094**Result** ✓ Passed**MOT #10** 2016-07-04 14:40**MOT test number** 427586120618**Result** ✓ Passed**MOT #9** 2016-07-04 10:37**MOT test number** 817732292579**Result** ✗ Failed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Pass with rectification Offside Registration plate lamp not working (1.1.C.1d)

**MOT #8** 2015-07-27 10:29**MOT test number** 199258105206**Result** ✓ Passed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Notice** Coolant leak**Advice** Offside Rear Radius arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Rear tyres feathering**Advice** Nearside Rear Radius arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Tail box mount corroded**MOT #7** 2014-09-02 11:14**MOT test number** 299595144220**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #6** 2013-09-18 09:25**MOT test number** 597461163279**Result** ✓ Passed**MOT #5** 2012-09-25 09:49**MOT test number** 508389662216**Result** ✓ Passed**MOT #4** 2012-09-25 09:49**MOT test number** 296069862246**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp not working on dipped beam (1.7.5a)



MOT #3	2011-09-26 16:59
MOT test number	237729061294
Result	✓ Passed
MOT #2	2011-09-22 10:02
MOT test number	487585161245
Result	✗ Failed
<div><div>Fail</div>Nearside Front Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)</div>	
MOT #1	2010-08-31 11:56
MOT test number	380183640401
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
26 September 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	26 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 GY57MGJ
Plate since	2019-09-29
Current registration	 GY57MGJ
Plate since	2019-09-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-09-18
Last registration	2023-09-09
Complete history	See info



Registration #1	2007-09-18	15 mi
Registration #2	2010-08-31	18.588 mi
Registration #3	2011-09-22	29.771 mi
Registration #4	2011-09-26	30.045 mi
Registration #5	2012-09-25	55.095 mi
Registration #6	2013-09-18	66.536 mi
Registration #7	2014-09-02	73.261 mi
Registration #8	2015-07-27	79.768 mi
Registration #9	2016-07-04	87.688 mi
Registration #10	2016-07-04	87.688 mi
Registration #11	2016-07-04	87.688 mi
Registration #12	2016-07-04	87.688 mi
Registration #13	2016-07-04	87.688 mi
Registration #14	2016-07-04	87.688 mi
Registration #15	2016-07-04	87.688 mi
Registration #16	2016-07-04	87.688 mi
Registration #17	2016-07-04	87.688 mi
Registration #18	2016-07-04	87.688 mi
Registration #19	2016-07-04	87.688 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1502 mm
Length	4081 mm
Wheel base	2515 mm
Kerb weight	1314 kg
Max. allowed weight	1680 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BFS 056261