





report date: 2024-03-28

General information

Make	MERCEDES
Model	CLS CLS320 CDI
Colour	Silver
Year of manufacture	2007
Top speed	148 mph
0 - 60 mph	7.0 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	221 BHP
Max. torque	510 Nm at 2.800 rpm
Engine capacity	2.987 сс
Cylinders	6
Fuel type	Diesel
Consumption city	27.2 mpg
Consumption extra urban	47.9 mpg
Consumption combined	27.7 mpg
CO2 emission	200 g/km
CO2 label	1



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-08-11

Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

MOT expiry date	2024-09-17
MOT pass rate	93 %
MOT passed	14
Failed MOT tests	1
Total advice items	20
Total items failed	2

MOT #15	2023-09-18 10:54
MOT test number	439264271976
Result	✓ Passed
Next expiry date	2024-09-17
Advice Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))	
Minor Nearside Front Suspension arm ball joint dust cover severely deteriorate	ed (5.3.4 (b) (i))

MOT #14	2023-09-16 09:06
MOT test number	953000976717
Result	× Failed
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))	
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Minor Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4	(b) (i))

MOT #13	2022-08-04 09:16
MOT test number	474850562142
Result	✓ Passed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/13



MOT #12 2021-05-11 14:16

MOT test number 741224743486

MOT #11 2020-04-14 10:29

MOT test number 923611605740

Result ✓ Passed

MOT #10 2019-04-16 08:57

MOT test number 990106733972

Result ✓ Passed

Advice Not possible to fully check brake pipes to rear of vehicle due to full length undertray and fuel tank

MOT #9 2018-05-14 13:46

MOT test number 323349757670

Advice Exhaust emissions high 2.15 /m

MOT #8 2017-05-08 10:56

MOT test number 818835740497

CarCheck.co.uk page 4/13



report date: 2024-03-28

2016-05-09 13:41 **MOT #7** 904141658103 **MOT test number** Result ✓ Passed **Advice** Nearside Front Torque/reaction arm has a slightly deteriorated rubber bush (2.4.G.2) N/s/f tyre poor condition/damaged on outer sidewall Advice Advice Offside Front Brake pipe slightly corroded (3.6.B.2c) Advice Long travel on parking brake lever Advice Offside Front Torque/reaction arm has a slightly deteriorated rubber bush (2.4.G.2) Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c) Advice Both front to rear brake pipes corroded slightly

MOT #6	2015-05-11 13:45
MOT test number	338621435164
Result	✓ Passed
Notice Slight surface corrosion all brake pipes	

MOT #5		2014-05-20 12:12
MOT test	number	276400544152
Result		✓ Passed
Advice	Nearside Front Brake pipe slightly corroded (3.6.B.2c)	
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Offside Front Brake pipe slightly corroded (3.6.B.2c)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #4	2013-05-13 12:47
MOT test number	157683933126
Result	✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #3	2012-05-21 11:00
MOT test number	269042442146
Result	✓ Passed
MOT #2	2011-05-31 10:20
MOT test number	257981451435
Result	✓ Passed
MOT #1	2010-06-07 10:54
MOT test number	552418650163
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check





Expires: 17 September 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	17 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date

Category


Type

Damage 2

Category

Date

Туре



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner history

e union matery	
For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downloaner.	

	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-07-04
Last registration	2023-09-18
Complete history	See info



Registration #1	2007-07-04	13 mi
Registration #2	2010-06-07	14.256 mi
Registration #3	2011-05-31	18.527 mi
Registration #4	2012-05-21	23.623 mi
Registration #5	2013-05-13	30.627 mi
Registration #6	2014-05-20	35.532 mi
Registration #7	2015-05-11	38.696 mi
Registration #8	2016-05-09	42.160 mi
Registration #9	2017-05-08	45.674 mi
Registration #10		11.117 es
Registration #11		
		11.777 46
Registration #12		1.77 4
Registration #12 Registration #13		1.77 m
		11.77 m
Registration #13		11.777 es 11.777 es 11.777 es
Registration #13 Registration #14		11.777 es 11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 12/13



Safety ratings

NCAP rating	r †
-------------	----------------

Video <u>see crash video</u>



Dimensions & weight

Width	2059 mm
Height	1403 mm
Length	4913 mm
Wheel base	2854 mm
Kerb weight	1815 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	4
Number of axles	2
Engine number	64292040446156

CarCheck.co.uk page 13/13