



TOYOTA



report date: 2024-03-29

General information

|                     |                 |
|---------------------|-----------------|
| Make                | TOYOTA          |
| Model               | RAV-4 D-4D XT-R |
| Colour              | Black           |
| Year of manufacture | 2009            |
| Top speed           | 118 mph         |
| Gearbox             | 6 speed Manual  |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 148 BHP             |
| Max. torque             | 340 Nm at 2.000 rpm |
| Engine capacity         | 2.231 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 39.2 mpg            |
| Consumption extra urban | 56.5 mpg            |
| Consumption combined    | 48.7 mpg            |
| CO2 emission            | 154 g/km            |
| CO2 label               | G                   |





Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-08-29                  |
| Pictures      | 1                           |
| Listing price | <a href="#">View report</a> |



source: [autotrader.co.uk](#)



MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2025-04-11 |
| MOT pass rate      | 67 %       |
| MOT passed         | 12         |
| Failed MOT tests   | 6          |
| Total advice items | 45         |
| Total items failed | 6          |

|                  |  |
|------------------|--|
| MOT #18          | 2024-04-04 09:30   |
| MOT test number  | 555314736946   |
| Result           | ✓ Passed   |
| Next expiry date | 2025-04-11   |
| Advice           | Offside Front Shock absorbers has light misting of oil (5.3.2 (b))   |
| Advice           | Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))  |
| Advice           | Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i)) |

|                 |  |
|-----------------|--|
| MOT #17         | 2024-03-19 12:02   |
| MOT test number | 412872233167   |
| Result          | ✗ Failed   |
| MAJOR           | Offside Front Service brake grabbing severely (1.2.1 (c))  |
| Advice          | Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i)) |
| Advice          | Offside Front Shock absorbers has light misting of oil (5.3.2 (b))   |
| Advice          | Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))  |

**MOT #16**

2023-03-22 09:52

**MOT test number**

999893591824

**Result**

✓ Passed

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #15**

2023-03-22 09:52

**MOT test number**

519608155914

**Result**

✗ Failed

- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #14** 2022-03-17 09:50**MOT test number** 770936813017**Result** ✓ Passed**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**MOT #13** 2021-04-12 14:34**MOT test number** 897913204496**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #12** 2021-04-12 09:07**MOT test number** 998411364256**Result** ✗ Failed**MAJOR** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**DANGEROUS** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**DANGEROUS** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #11** 2019-05-01 14:09**MOT test number** 883949341995**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Advise undertrays fitted

**MOT #10** 2019-05-01 09:00**MOT test number** 933000045446**Result** ✗ Failed**Advice** Child Seat fitted not allowing full inspection of adult belt**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Advise undertrays fitted**MOT #9** 2018-04-30 15:28**MOT test number** 931361950160**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #8** 2018-04-30 12:26**MOT test number** 349703997364**Result** ✗ Failed**Advice** Child Seat fitted not allowing full inspection of adult belt**Fail** Offside Rear Anti-roll bar linkage missing (2.4.G.1)**MOT #7** 2017-03-29 13:32**MOT test number** 942842470233**Result** ✓ Passed**MOT #6** 2016-02-26 17:00**MOT test number** 856868714229**Result** ✓ Passed

**MOT #5** 2016-01-21 12:32**MOT test number** 107135797329**Result** ✓ Passed**Advice** Handbrake reading low**MOT #4** 2014-10-23 11:18**MOT test number** 977826794274**Result** ✓ Passed**MOT #3** 2013-09-18 17:22**MOT test number** 466811863258**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2013-09-18 10:26**MOT test number** 628851463272**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Fail** Offside Headlamp aim too low (1.8)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Headlamp aim too low (1.8)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2012-09-27 16:24**MOT test number** 296421272258**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
11 April 2025

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 October           |
| <b>Days left</b>        | 156                             |
| <b>MOT expiry date</b>  | 11 April 2025                   |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |            |
|--|------------|
| <b>Vehicle class</b>                           | 49         |
| <b>Band</b>                                    | G          |
| <b>Single payment (12 months)</b>              | £ 240,00,- |
| <b>Single six month payment</b>                | £ 132,00,- |
| <b>Total payable by 12 monthly instalments</b> | £ 252,00,- |





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,299 |
| Auction value               | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |              |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 1          |
| Current registration | SY59BYM    |
| Plate since          | 2019-03-29 |
| Current registration | SY59BYM    |
| Plate since          | 2019-03-29 |

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 20                       |
| First mileage registration | 2009-09-21               |
| Last registration          | 2024-04-04               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2009-09-21 | 7 mi      |
| Registration #2  | 2012-09-27 | 27.198 mi |
| Registration #3  | 2013-09-18 | 35.997 mi |
| Registration #4  | 2013-09-18 | 35.997 mi |
| Registration #5  | 2014-10-23 | 44.189 mi |
| Registration #6  | 2016-01-21 | 47.728 mi |
| Registration #7  | 2016-02-26 | 48.029 mi |
| Registration #8  | 2017-03-29 | 54.651 mi |
| Registration #9  | 2018-04-30 | 63.182 mi |
| Registration #10 | 2018-04-30 | 63.182 mi |
| Registration #11 | 2019-05-20 | 71.277 mi |
| Registration #12 | 2019-05-20 | 71.277 mi |
| Registration #13 | 2019-05-20 | 71.277 mi |
| Registration #14 | 2019-05-20 | 71.277 mi |
| Registration #15 | 2019-05-20 | 71.277 mi |
| Registration #16 | 2019-05-20 | 71.277 mi |
| Registration #17 | 2019-05-20 | 71.277 mi |
| Registration #18 | 2019-05-20 | 71.277 mi |
| Registration #19 | 2019-05-20 | 71.277 mi |
| Registration #20 | 2019-05-20 | 71.277 mi |

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1815 mm |
| Height              | 1685 mm |
| Length              | 4335 mm |
| Wheel base          | 2560 mm |
| Kerb weight         | 1650 kg |
| Max. allowed weight | 2190 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 60 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 5                |

|                        |            |
|------------------------|------------|
| <b>Number of axles</b> | 2          |
| <b>Engine number</b>   | 2AF0279000 |